OKI

ES3037/3037E
Color LED Page Printer
MAINTENANCE
MANUAL

ODA/OEL/INT

030919B

Document Revision History

Rev.No.	Date	Corrected items			Person in change
		No.	Page	Description of change	
1	2002-10-23				
2	2002-11-29				NP11 Haruyama
3	2003-06-06	2.3, 7	22,157	Part No. of the Control Panel Bezel	ME4　Ueda

PREFACE

This maintenance manual provides procedures and techniques for the troubleshooting, maintenance, and repair of ES3037/3037E.

This manual is written for maintenance personnel, but it should always be accompanied with the ES3037/3037E User's Manual for procedures for handling and operating ES3037/3037E. For repairing each component of ES3037/3037E, see the Troubleshooting manual.

[Notices]
The contents of this manual are subject to change without prior notice.
Although reasonable efforts have been taken in the preparation of this manual to assure its accuracy, this manual may still contain some errors and omissions. OKI will not be liable for any damage caused or alleged to be caused, by the customer or any other person using this maintenance manual to repair, modify, or alter ES3037/3037E in any manner.

[Warning]
Many parts of ES3037/3037E are very sensitive and can be easily damaged by improper servicing. We strongly suggest that ES3037/3037E be serviced by OKI's authorized technical service engineers.

CONTENTS

1. SPECIFICATIONS

1.1 Basic System Configuration

The basic system configuration of ES3037/3037E is illustrated in Figure 1.1.

Figure 1.1

1.2 Printer Engine Specifications

The inside of the printer is composed of the followings:

• Electrophotographic Processor
• Paper Paths
• Controller Block (CU and PU)
• Operator Panel
• Power Units (High-Voltage Unit and Low-Voltage Unit)

Figure 1-2 shows the printer configuration.

Figure 1.2

1.3 Option Configuration

The followings are available as options on ES3037/3037E.

(1) 2nd Tray/ 3rd Tray

Note: Don't use one for

C9200/C9400

(2) Duplex Unit

Note: Don't use one for

C9200/C9400

(3) High-Capacity Tray

Note: Don't use one for

C9200/C9400

(4) Expansion Memory 64/128/256/512MB

Note: Don't use one for

C9200/C9400

(5) Internal Hard Disk

Note: Don't use one for

C9200/C9400

(6) Ethernet Board

Note: Don't use one for

C9200/C9400

(7) Finisher Unit

(8) Simplified Color Copy Unit * Equipped with exclusive auto feeder

(9) Dual-Purpose Finisher and Copy Unit Table, and Copy Unit Extension Rack

Color Copy Unit Extension Rack

Dual-Purpose Finisher and Copy Unit Table

(10) 2nd/3rd Tray Unit on Casters

Note: Don't use one for

C9200/C9400

1.4   Specifications

(1) External Dimensions   Height: 460mm   Width: 666mm   Length: 626mm

(2) Weight   72 kg

(3) Paper   Type: Ordinary paper and transparencies (Recommended: ML
                                     OHP01)
                            Size: Postal card, Legal 13" or 14", Executive, A4, A5, B5, A6,
                                     A3 A3-Nobi, B4
                                     (Only the 1st tray and the front feeder support A6 and
                                     postal card sizes.)
                            Weight: 1st tray   17 lb to 54 lb (64 to 203g/m^2)
                                    Multi Purpose feeder   17 lb to 54 lb (64 to 203g/ m^2)

(4) Print Speed   Color: 30 pages per minute
     (A4 LEF)   (Transparency: Pages per minute)
                            Monochrome: 37 pages per minute
                                            (Transparency: Pages per minute)
                            Postal Card, Label, Thick Paper: 12Pages per minute

(5) Resolution   600 x 600 dots per inch (C9300)
                            1200 × 1200 dots per inch (C9500)

(6) Power Input   115V~127V , 220V~240V

(7) Power Consumption   Peak: 1600W   Normal Operation: 800W (5% duty)
                            Idle: 250W   Power Saving Mode: 70W

(8) Frequency   50Hz or 60Hz±2Hz

(9) Noise   Operating: 55 dB (without Option units)
                            Standby: 45 dB
                            Power Saving: 43 dB

(10) Consumable Life   Toner Cartridge: 7,500 pages (5% duty)
                            Large-Capacity Toner Cartridge: 15,000 pages (5% duty)
                                                                (in each of Y, M, C and K)
                            Image Drum: 26,000 pages (5% duty, Continuous printing)
                                                (in each of Y, M, C and K)

(11) Parts Replaced Periodically
                            Fuser Unit Assy: Every 80,000 pages
                            Belt Cassette Assy: Equivalent of 80,000 pages (3P/J)
                            Transfer Belt cartridge: 60,000 prints

(12) Temperatures and Relative Humidities

Temperature

	Temperature (°F)	Temperature (°C)	Remark
Operating	50 to 89.6	10 to 32	17 to 27°C (Temperatures to assure full color print quality)
Non-Operating	32 to 109.4	0 to 43	Power-off
Storage (Max. One Year)	-14 to 109.4	-10 to 43	With drum and toner
Transport (Max. One Month)	-20 to 122	-29 to 50	With drum and without toner
Transport (Max. One Month)	-20 to 122	-29 to 50	With drum and toner

Humidity

	Relative Humidity (%)	Max. Wet-Bulb Temperature (°C)	Remark
Operating	20 to 80	25	50 to 70% (Humidities to assure full color print quality)
Non-Operating	10 to 90	26.8	Power-off
Storage	10 to 90	35	
Transport	10 to 90	40	

(13) Printer Life   1,000,000 pages (on a A4 basis) or five years

2. PARTS REPLACEMENT

This section describes the procedure for replacing the parts, assemblies and units in the field. The replacing procedure is given for detachment. To attach, use the reverse procedure.

2.1 Precautions in Replacing Parts

(1) Before replacing the parts, be sure to remove the CA cable and the interface cable.
   (a) To remove the AC cable, always use the following procedure.
      ① Flip the power switch of the printer off (to "O").
      ② Pull the AC inlet plug of the AC cable out of the AC receptable.
      ③ Remove the AC cable and the interface cable from the printer.

   (b) To connect the printer again, always use the following procedure.
      ① Connect the AC cable and the interface cable to the printer.
      ② Insert the AC inlet plug into the AC receptacle.
      ③ Flip the power switch of the printer on (to "I").

(2) Do not disassemble the printer so long as it operates properly.
(3) Minimize the disassembly. Do not detach parts other than those shown in the replacing procedure.
(4) For maintenance applications, use designated tools.
(5) Follow the order instructed to disassemble the printer. Incorrect order may damage the parts.
(6) Small parts such as screws and collars tend to get lost, so temporarily place and fix them in their original positions.
(7) When handling ICs and circuit boards such as microprocessors, ROMs and RAMs, do not use gloves that likely to have static.
(8) Do not place the printed circuit boards directly on the printer or the floor.

[Maintenance Tools]

Table 2-1 lists tools necessary to replace the units.

Table 2-1 Maintenance Tools

No.	Service Tools		Q' ty	Place of use	Remarks
1		No. 1-100 Philips screwdriver	1	2~2.5 mm screws	
2		No. 2-200 Philips screwdriver, Magnetized	1	3~5 mm screws	
3		No. 3-100 screwdriver	1		
4		No. 5-200 screwdriver	1		
5		Digital multimeter	1		
6		Pliers	1		
7		Handy cleaner	1		
8		LED Head cleaner P/N 4PB4083-2248P001	1	Cleans LED head	
9		High voltage probe	1		
10	Label	Transparency sheet (thickness premeasured) 42404301	1	Adjustment for Media Thickness sensor	
11		Stage height adjustment jig 42423701	1	Adjustment for Media Thickness sensor	
12		⊖Microdriver 2.0mm	1	Adjustment for Lever adjust (Media Thickness)	

2.2   Parts Layout

Figure 2.1

[Top Cover Assy]

Figure 2.2

[Printer Unit-1/2]

Figure 2.3

[Printer Unit-2/2]

Figure 2.4

[Cassette Guide Assy (L), (R)]

Figure 2.5

Figure 2.6

[Duplex Unit]

Figure 2.7

2.3   Replacing Parts

This section describes how to replace the parts and assemblies illustrated below.

```
ES3037/3037E 41960434, 41960432
             Print Engine Controller PWB (2.3.23)
             41970801 × 4, 41971201 × 4
             LED Assy (2.3.2)
             41863002
             Power-Unit AC-DC Switching (115V) (2.3.35)
             41870802
             Power-Unit AC-DC Switching (230V) (2.3.35)
             42046801
             HV Power Supply (2.3.36)
             41946101, 41946105, 41946103, 41946109
             Fuser Unit (2.3.38)
             41946001, 41946003, 41946009
             Belt Unit (2.3.39)
             41945701, 41945703
             Duplex Unit (2.3.40)
             42542704, 42542705, 42542709, 42542710
             Control panel Bezel (2.3.4)
             41484915
             Cassette Assy (2.3.7)

    419413xx ──── 41941401 ──── 41941501 ──────────── 40841301
    Printer NIP   Printer Unit   Printer Chassis (2.3.24)   Fuser Latching Handle (L) (2.3.30)
                                 41483206                    41628301
                                 Regist Roller Assy (A) (2.3.16)   Fuser Latching Handle Spring (2.3.30)
                                 41483302                    40841601
                                 Regist Roller Assy (B) (2.3.17)   Entrance Sensor Actuator #1 (2.3.25)
                                 41483406                    41578501
                                 Registration Motor Assy (2.3.18)   Entrance Sensor Actuator #2 (2.3.27)
                  41483702       41187102                    40841801
                  Main Motor FAN Assy (2.3.28)   Registration Clutch (2.3.18)   Entrance Sensor Actuator #3 (2.3.27)
                                 41486801                    41744006
                                 Duplex Guide Assy (2.3.21)   Registration Shutter Solenoid Assy
                  41481006 ──── 41481306                     41947701
                  Unit-Lower-Frame   Main Feed Assy (2.3.37)   Registration Shutter
                  (2.3.37)    41481106 ──── 41950401         42030001
                              Frame Assy Lower   PCE-Size Sence (2.3.37)   Registration Shutter Spring
                              41481203      2201000P0140      42170901
                              Right Side Cover (2.3.7)   IMSA-9714N-14Z02 (2.3.37)   Fuser Driver Gear-A (2.3.28)
                  41500101                                   41095901
                  Insurator                                  Fuser Exit Roller (2.3.28)
                  41431602                                   4PP4043-4489P001
                  ID Cooling Fan (2.3.19)                    Fuser Exit Roller Bushing (L) (2.3.28)
                  2381023P0004                               4PP4076-3949P001
                  HV Tape Harness                            Fuser Exit Roller Bushing (R) (2.3.28)
                  41484101 ──── 41490703                     41189701 × 4
                  Electrical Chassis (2.3.22)   Electrical Chassis Cooling Fan   Drum Contact Assy (2.3.14)
                  41483806      40863801                     41258301
                  Main Motor Assy (2.3.33)   Plate-Side (2.3.22)   Entrance Sensor PWB (2.3.26)
                  41483906 ──── 40841401                     41947801
                  Belt Motor Assy (2.3.31)   Fuser Latching Handle (R) (2.3.32)   Color Registration Sensor Assy (2.3.20)
                  40850206      41628301                     41073602
                  Contact Assy (2.3.34)   Fuser Latching Handle Spring (2.3.32)   Exit Sensor Assy (2.3.29)
                  41484001                                   42199601
                  Plate Assy-Side (2.3.34)                   Waste Toner Sensor Actuator (2.3.27)
                  41276501
                  Rear Cover (2.3.12)
                  41277401
                  Left Side Cover (2.3.9)
                  41481203
                  Right Side Cover (2.3.7)
                  41749602, 41276401
                  Front Cover (2.3.11)
                  41484201
                  Face Up Tray (2.3.10)
                  xxxxxxxx ────────────────────── 42216201 × 8
                  Top Cover                       LED Assy Spring (2.3.2)
                  41484401                        42124802, 41960902
                  Top cover (2.3.1)               LED Control PWB (2.3.4)
                  41493013, 41493014 ──── 41045801 × 2   41349801
                  Multipurpose Tray Assy (2.3.13)   Link (2.3.13)   Stack Full Sensor (2.3.4)
                  41764102, 41764103      41484603   41484504
                  MT Top Cover (2.3.13)   MT Tray Cover Assy (2.3.13)   Control Panel Assy (2.3.4)
                  41277901                40325101   2381003P0018, 2381003P0031
                  Cover-Blind (2.3.7)     MT Drive Gear (2.3.13)   Control Panel Tape Harness (2.3.4)
                  41886901                        42169501
                  Thickness Plate Assy (2.3.15)   LED Harness K
                  41928801                        42169502
                  Stage -Pickup (2.3.16)          LED Harness Y
                  41911101                        42169503
                  Thickness Sensor Assy (2.3.15)   LED Harness M
                  41888701                        42169504
                  Cover Seal Sensor (2.3.15)      LED Harness C
                                                  41328401
                                                  Top Cover Handle (2.3.5)
                                                  41277601
                                                  Top Cover Latch (2.3.5)
                                                  40861401 × 2
                                                  Top Cover Latch Spring (2.3.5)
                                                  41349301 × 4
                                                  Eject Roller (2.3.4)
                                                  41947901
                                                  Eject Guide Assy (2.3.6)
```

2.3.1   Top cover

(1)   Open the top cover Assy.

(2)   Unscrew 9 screws ① to detach the top cover ②.

Figure 2-3-1   Top Cover

2.3.2   LED Head / LED Spring / Post-Guide

(1)   Open the Top Cover ①.

(2)   Unplug 3 cables, release 2 hooks and remove the LED Head ②.
(At this time, the 2 springs ③, Post-Guide ④ become detached together with the LED Head ②.)

Note!   The contact is used only for 1200 dpi K, Y and M.

Figure 2-3-2   LED Head / LED Spring / Post-Guide

2.3.3 Top Cover Unit

(1) Remove the Top Cover. (See Sec. 2.3.1.)

(2) Remove the Rear Cover. (See Sec. 2.3.12.)

(3) Remove the Front Cover (See Sec. 2.3.11.)

(4) Remove the Electrical Chassis. (See Sec. 2. 3. 22.)

(5) Unscrew the screws ① and ②, and remove the Limiters (F) ③ and (R) ④.

(6) Remove the Inner Shaft ⑤ and then the Top Cover Unit ⑧. At this time, the Inner Springs ⑥.

   and ⑦ also come off.

Figure 2-3-3   Top Cover Unit

2.3.4 Control Panel Assy / Control Panel Bezel / LED Control PWB / Toner Sensor / Stack Full Sensor / Control Panel / Control Panel Tape Harness / Eject Roller

    (1) Remove the Control Panel Bezel ①.

    (2) Unscrew the screws ② and remove the Control Panel ③.

    (3) Remove the Control Panel Tape Harness ④.

    (4) Unscrew the screws ⑤, unplug the connectors ⑥ and then remove LED Control PWB ⑦.

    (5) Unscrew the screws ⑧ and remove the plate ⑨.

    (6) Release the claw and remove the Toner Sensor ⑩.

    (7) Remove the Stack Full Sensor ⑪.

    (8) Unscrew the screw ⑫ and remove the Eject Sensor Bracket ⑬.

Figure 2-3-4　Control Panel Assy / Control Panel Bezel / LED Control PWB / Toner Sensor / Stack Full Sensor / Control Panel / Control Panel Tape Harness / Eject Roller

2.3.5　Top Cover Handle / Top Cover Latch / Top Cover Latch Spring

(1)　Unscrew 2 screws ① and remove the Top Cover Handle ② and Top Cover Latch ③.
(At this time, 2 Top Cover Latch Springs ④ also come off.)

Figure 2-3-5　Top Cover Handle / Top Cover Latch / Top Cover Latch Spring

2.3.6   Eject Guide Assy

(1)   Unscrew 7 screws ① and remove the Eject Guide Assy ②.

Figure 2-3-6   Eject Guide Assy

2.3.7   Cassette Assy / Cover-Blind / Side Cover Assy

    (1)   Take out the Cassette Assy ①.

    (2)   Release 2 joints and remove the Cover-Blind ②.

    (3)   Unscrew 2 screws ③ and remove the stopper ④.

    (4)   Unscrew 5 screws ⑤, release the claw at the left support of the Side Cover (R) and remove the Side Cover (R) ⑥.

Figure 2-3-7   Cassette Assy / Cover-Blind / Side Cover Assy

2.3.8   Feed Roller

    (1)   Take out the Cassette. (See Sec. 2.3.7.)

    (2)   Release the latch and remove the Feed Rollers ①.

Figure 2-3-8   Feed Roller

2.3.9   Left Side Cover

(1)   Unscrew 4 screws ① and remove the Left Side Cover ②.

Figure 2-3-9   Left Side Cover

2.3.10 Face Up Tray

(1)   Open the Face Up Tray ① to the arrow direction, release the joints of the Links ② (2 joints each) and then remove the Face Up Tray ①.

Figure 2-3-10   Face Up Tray

2.3.11 Front Cover

(1) Open the Top Cover ①.
(2) Release 2 claws at the Side Cover (R) and remove the Blind Cover ②.
(3) Unscrew 6 screws ③ and remove the Front Cover ④.

Figure 2-3-11   Front Cover

2.3.12 Rear Cover

(1) Open the Top Cover ①.

(2) Unscrew 6 screws ② and a screw ③, and remove the Rear Cover ④.

Figure 2-3-12   Rear Cover

2.3.13 Multipurpose Tray Assy / Multipurpose Tray Cover Assy / Link / Multipurpose Tray Top Cover / Multipurpose Tray Drive Gear / OHP Sensor

(1) Remove the Rear Cover (See Sec. 2.3.12.)

(2) Remove the Front Cover (See Sec. 2.3.11.)

(3) Unscrew 3 screws ① and remove Multipurpose Tray Top Cover ②.

(4) Remove the Cover Seal Sensor and the sensor connector.

(5) Release the joints between ④ and ⑤, and remove Multipurpose Tray Cover Assy ⑤.
(At this time, the Links ⑥ also comes off.)

(6) Release a hook and remove the Multipurpose Tray Drive Gear ⑦.

Figure 2-3-13 Multipurpose Tray Assy / Multipurpose Tray Cover Assy / Link / Multipur-
pose Tray Top Cover / Multipurpose Tray Drive Gear / OHP Sensor

[OHP Sensor Replacement]

(7) Figure 2-3-13-1 shows the bottom of the multipurpose tray ④. First remove the cover ⑨ (figure 2-3-13-1). The cover ⑨ with five protrusions can be disengaged by removing them with a screwdriver etc.

(8) Remove the OHP sensor ⑩ (figure 2-3-13-1). Only the sensor, which has the shape shown in figure 2-3-13-2, can be detached by pushing those claws on its both sides which are shaded in the figure, using a flatblade screwdriver etc. Be careful not to allow the cable attached to the sensor to be broken.

Figure 2-3-13-1 Bottom of Multipurpose Tray

Figure 2-3-13-2 OHP Sensor Composition

Note! When cleaning the OHP sensor, wipe dirt such as paper powder off its sensing surface that is as shown in figure 2-3-13-3, with a soft cloth or the tip of a brush. The shaded areas, which are lenses, should be wiped especially carefully, taking care not to allow it to be scratched.

Figure 2-3-13-3 Top of OHP Sensor

2.3.14 Drum Contact Assy

(1) Insert a screwdriver between the Printer Chassis and Drum Contact Assy ①, and remove the Drum Contact Assy ①.

Figure 2-3-14   Drum Contact Assy

2.3.15   Media Thickness Sensor Assy

(1)   Detach the Cover Seal Sensor ① and the Thickness Sensor Connector ②.

(2)   Remove the two screws ③ to demount the Media Thickness Assy.

(3)   Insert a microdriver(-) between the Thickness Plate Assy ④ and Thickness Sensor Assy ⑤ to demount the Thickness Sensor Assy ⑤

Note!   When attaching the Media Thickness Assy, adjust [Spin lever adjust by microdriver(-)] the position of lever (White).

The upper surface of the lever be in agreement with a datum level. (Adjustment range 0/-0.5mm)

Figure 2-3-15   Media Thickness Sensor Assy

2.3.16 Registration Roller Assy (A) / Registration Drive Gear (A)

(1) Remove the Front Cover. (See Sec. 2.3.11.)

(2) Remove the Rear Cover. (See Sec. 2.3.12.)

(3) Remove the Multipurpose Tray. (See Sec. 2.3.13.)

(4) Remove the Media Thickness Sensor Assy. (See Sec. 2.3.15.)

(5) Remove the screw ① of the Pickup Stage ②.

(6) Remove the four screws ③ to demount the registration roller Assy (A) ④and the Pickup Stage ②.

(7) Remove the E ring ⑤ to detach the registration gear (A) ⑥.

Note! When attaching the pickup stage ①, place the stage height adjustment jig between the pressure roller and the registration roller and, until the top surface of the pickup stage reaches the jig, move the pickup stage toward the jig. (See Table 2-1 Maintenance Tools)

Figure 2-3-16   Registration Roller Assy (A) / Registration Drive Gear (A)

2.3.17 Registration Roller Assy (B)

    (1) Take out the Cassette Assy.

    (2) Remove the Front Cover. (See Sec. 2.3.11.)

    (3) Remove the Rear Cover. (See Sec. 2.3.12.)

    (4) Remove the Electrical Chassis. (See Sec. 2. 3. 22.)

    (5) Remove the Registration Clutch. (See Sec. 2.3.18.)

    (6) Remove the Printer Unit Chassis. (See Sec. 2.3.24.)

    (7) Unscrew 4 screws ① and pull out the Registration Roller Assy (B) ② to the arrow direction.

Figure 2-3-17   Registration Roller Assy (B)

2.3.18 Registration Clutch / Registration Motor Assy

    (1) Remove the Left Side Cover. (See Sec. 2.3.9.)

    (2) Remove the Electrical Chassis. (See Sec. 2. 3. 22.)

    (3) Unplug the connector, take out the E Ring ① and dismount the Registration Clutch ②. Unscrew the screws ③ and ④, and remove the Earth Plate ⑤.

    (4) Unplug the connector, unscrew 2 screws ⑥ and remove the Registration Motor Assy ⑦.

Figure 2-3-18   Registration Clutch / Registration Motor Assy

2.3.19 ID Cooling Fan

(1) Unplug the connector ①, unscrew the screws ② and remove the ID Cooling Fan ③.

Note! When mounting the fan, pay attention to the mounting direction.

air direction

Figure 2-3-19   ID Cooling Fan

2.3.20 Color Registration Sensor Assy

    (1) Unscrew 2 screws ①, unplug 3 connectors and remove the Color Registration Sensor Assy ②.

    (2) Remove the Earth Plate (B) ③.

Connectors

Figure 2-3-20   Color Registration Sensor Assy

2.3.21 Duplex Guide Assy

(1) Release the latch and remove the Duplex Guide Assy ①.

(2) Remove the springs ②.

Main Chassis (L)

Figure 2-3-21   Duplex Guide Assy

2.3.22 Electrical Chassis / Electrical Chassis Cooling Fan

(1) Unscrew 5 screws ① and 2 screws ②, and remove the Plate (A) ③.

(2) Unscrew 31 screws ④ and remove the Shield Plate (B) ⑤.

(3) Remove the Printer Engine Controller PWB. (See Sec. 2.3.23.)

(4) Unscrew 11 screws ⑥ and remove the Electrical Chassis ⑦.

(5) Unscrew 2 screws ⑧ and remove the Electrical Chassis Cooling Fan ⑨.

Figure 2-3-22 Electrical Chassis / Electrical Chassis Cooling Fan

2.3.23 Print Engine Controller PWB

    (1) Remove the Rear Cover. (See Sec. 2.3.12.)

    (2) Remove the Electrical Chassis and Electrical Chassis Cooling Fan. (See Sec. 2.3.22.)

    (3) Unscrew 5 screws ①, unplug all the connectors and remove the Print Engine Controller PWB ②.

Figure 2-3-23   Print Engine Controller PWB

2.3.24 Printer Unit Chassis

(1) Open the top cover.

(2) Remove the fuser unit (see section 2.3.38).

(3) Remove the belt unit (see section 2.3.39).

(4) Remove the top cover unit (see section 2.3.3).

(5) Remove the eject guide Assy (see section 2.3.6).

(6) Remove the side cover (R) (see section 2.3.7).

(7) Remove the face-up tray Assy (see section 2.3.10).

(8) Remove the side cover (L) (see section 2.3.9).

(9) Remove the registration clutch and the registration motor Assy (see section 2.3.18).

(10) Remove the duplex guide Assy (see section 2.3.21).

(11) Unscrew the screw ① and remove the AC switch assy ②.

(12) Unscrew the 5 black screws ③ and other 7 screws ④, then detach the printer unit chassis ⑤.

Figure 2-3-24   Print Unit Chassis

2.3.25 Entrance Cassette Sensor Actuator

    (1) Remove the Printer Unit Chassis. (See Sec. 2.3.24.)

    (2) Turn over the Main Chassis.

    (3) Release 2 clamps with tweezers and remove the Entrance Cassette Sensor Actuator ①.

Main chassis

Figure 2-3-25   Entrance Cassette Sensor Actuator

2.3.26 Entrance Sensor PWB (R71)

(1) Remove the Registration Roller Assy B. (See Sec. 2.3.17.)

(2) Unscrew 2 screws ① and remove the Entrance Sensor PWB ②.

Figure 2-3-26   Entrance Sensor PWB

2.3.27 Entrance MT Sensor Actuator / Entrance Belt Sensor Actuator / Entrance Waste Toner Sensor Actuator

    (1)   Remove the Entrance Sensor PWB (R71). (See Sec. 2.3.26.)

    (2)   Release the latch and remove the Entrance MT Sensor Actuator ①.

    (3)   Release the latch and remove the Entrance Belt Sensor Actuator ②.

    (4)   Release the latch and remove the Entrance Waste Toner Sensor Actuator ③.

Figure 2-3-27   Entrance MT Sensor Actuator / Entrance Belt Sensor Actuator /
Entrance Waste Toner Sensor Actuator

2.3.28 Main Cooling Fan (PULL) Assy / Main Cooling Fan (PUSH) / Fuser Eject Roller

(1) Unscrew 2 screws ① and remove the Main Cooling Fan (PULL) Assy ②.

(2) Unscrew the screw ③ and remove the Fuser Eject Roller Contact ④.

(3) Remove the Fuser Drive Gear ⑤.

(4) Unscrew the screw ⑥ and remove the Fuser Drive Gear Assy ⑦.

(5) Unscrew the screws ⑧, take out the washers ⑨ and remove the Main Cooling Fan (PUSH) ⑩.

(6) Release the latch and remove the Fuser Eject Roller Bearing (L) ⑪ and Fuser Eject Roller ⑫.

Figure 2-3-28   Main Cooling Fan (PULL) Assy / Main Cooling Fan (PUSH) / Fuser Eject Roller

2.3.29 Eject Sensor Assy

 (1) Remove the Fuser Eject Roller. (See Sec. 2.3.28.)

 (2) Unscrew the screw ①, unplug the connector and remove the (red/blue) Eject Sensor Assy ②.

Figure 2-3-29 Eject Sensor Assy

2.3.30 Fuser Latch Handle (L)

(1) Remove the Latch Handle Spring ①.

(2) Unscrew the screw ② and remove the Fuser Latch Handle (L) ③.

Figure 2-3-30   Fuser Latch Handle (L)

2.3.31 Belt Motor Assy

    (1) Remove the Fuser Latch Handle (R). (See Sec. 2.3.32.)

    (2) Unscrew 2 screws ① and unplug 2 connectors ②.

    (3) Remove the Belt Motor Assy ③.

Figure 2-3-31 Belt Motor Assy

2.3.32 Fuser Latch Handle (R)

(1) Remove Printer Unit Chassis. (See Sec. 2.3.24.)

(2) Take out the E Ring ①.

(3) Release the Fuser Latch Handle Spring ② and remove the Fuser Latch Handle (R) ③.

Figure 2-3-32   Fuser Latch Handle (R)

2.3.33 Main Motor Assy

    (1) Remove the Belt Motor Assy. (See Sec. 2.3.31.)

    (2) Unplug all the connectors.

    (3) Unscrew 2 screws ① and remove the Main Motor Assy ②.

Figure 2-3-33   Main Motor Assy

2.3.34 Contact Assy / Side Plate Assy

(1) Remove the Printer Unit Chassis. (See Sec. 2.3.24.)

(2) Unscrew 4 screws ① and remove the Side Plate Assy ②.

(3) Unscrew the screws ③ and remove the Contact Assy ④.

Figure 2-3-34   Contact Assy / Side Plate Assy

2.3.35 Low-voltage Power Unit

    (1)   Remove the Printer Unit Chassis. (See Sec. 2.3.24.)

    (2)   Unplug the connector ①.

    (3)   Unscrew 6 screws ② and remove Low-voltage Power Unit ⑤.

    (4)   Unplug the connector ③.

    (5)   Unscrew the screw ⑥, release the claw at the AC Switch ⑦ and remove the plate ⑧.

    (6)   Unscrew the screws ⑨ and ⑩, and remove the AC Inlet ⑪ from the plate ⑫.

Figure 2-3-35   Low-voltage Power Unit

2.3.36 High-voltage Power Unit

    (1)   Remove the Contact Assy. (See Sec. 2.3.34.)

    (2)   Remove the connector of the High-voltage Power Unit ①.

    (3)   Unscrew 2 screws ② and remove the High-voltage Power Unit ① and HV Tape Harness ③.

Figure 2-3-36   High-voltage Power Unit

2.3.37 Main Feeder Assy

(1) Remove the Printer Unit Chassis. (See Sec. 2.3.24.)

(2) Remove the Low-voltage Power Unit and High-voltage Power Unit. (See Secs. 2.3.35 and 2.3.36.)

(3) Unscrew 5 screws ① and remove the Lower Plate ②.

(4) Unscrew 6 screws ③ and remove the Main Feeder Assy ④.

(5) Unscrew the screws ⑤, disconnect the cable and remove the Paper Size Sensor PWB ⑥.

(6) Unscrew the screw ⑦ and remove the Duplex Connector ⑧.

(7) Unscrew the screws ⑨ and remove the Second Tray Connector ⑩.

Figure 2-3-37   Main Feeder Assy

2.3.38 Fuser Unit

    (1) Open the Top Cover ①.

    (2) Push the left/right Fuser Levers (blue) ② to the arrow direction and remove the Fuser Unit ③.

Figure 2-3-38   Fuser Unit

2.3.39 Belt Unit

    (1)   Open the Top Cover ①.

    (2)   Remove the I/D Unit.

    (3)   Push the lever (blue) ② to the arrow direction and pull the handle (blue) upward to remove the Belt Unit ③.

Figure 2-3-39   Belt Unit

2.3.40 Duplex Unit

(1) Pull the lever ② of the duplex unit ① to slide out the unit ① toward the front, and detach the unit ① by pulling its front upward.

(2) Turn the lever ③ of the duplex unit ① toward the front, then pull the lever ④ toward the front to check to see that the pin ⑤ moves up.

(3) The duplex unit ① can be separated from the cassette Assy by moving the unit up.

Figure 2-3-40　Duplex Unit

2.3.41 CU Assy

   (1) Pulling out Controller Board
      1. Undo the two screws ①.
      2. Pull the controller board ② out.
      3. Place the controller board ② on a flat table.

   (2) Detaching Fan
      1. Remove the connector ③.
      2. Unscrew 2 screws ④.
      3. Remove the CPU Cooling Fan ⑤.

Figure 2-3-41 CU Assy (1/2)

(3) Demounting TIG Board
1. Remove 3 screws ⑥ and screw ⑦ ,and remove the fan bracket ⑧.
2. Remove the screw ⑨ and 4 screws ⑩ ,and remove the plate support ⑪ and the guide rail A⑫.
3. Remove 2 screws ⑬ ,and remove the guide rail B⑭.
4. Remove 2 screws ⑮ and 2 screws ⑯ and the plate-FG(Centro)⑰, then demount the TIG board ⑱.

Figure 2-3-41 CU Assy (2/2)

3. ADJUSTMENT

This device is adjusted by key input from the operator panel.

Other than the general menu, this device supports a maintenance menu. Select the menu that matches your objective.

3.0 System Maintenance MENU

The printer enters this mode when you turn on the power supply switch while holding down the [Menu]+[Item]+[Value]+[Cancel] (0+1+6+7)switches.

This menu is not disclosed to end-users because changes can be made to brand/destination, etc.

Table 3-0 (1/2) Maintenance Menu display Table

Category	Item(1st Line)	Value(2nd Line)	DF	Functions
OKIUSER	OKIUSER	ODA OEL APS JP1 JPOEM1 OEMA OEML	*	Sets Brand JPOEM1: Japan OEM OEMA: Overseas OEM for A4 default OEML: Overseas OEM for Letter default Boots up automatically when the Menu is existed.

CONFIGURATION MENU	ENGINE SPEED	HIGH
		LOW
			*	For swithing the engine speed between the overseas 16/24PPM model and the 20/24PPM model.
				(Valid only for PX711 600dpi Head)
				  HIGH: 20/24PPM model (C7300)
				  LOW : 16/24PPM model (C7100)
				Reboots automatically as the menu is exited.
				
				 note: This function for PX713 is ignored.

	HIGH RESOLUTION	ENABLE DISABLE	*	Not used. note: Don't change the setting value.
ENG STATUS PRINT	ENG STATUS PRINT	EXECUTE		Selecting by the Select switch, then pressing the On-line switch will prompt initialization and printing Engine information.
TEST PRINT MENU	TEST PRINT MENU	ENABLE DISABLE	*	Switches ENABLE and DISABLE to display the TEST PRINT MENU category in the User Menu. (See "ID Check Pattern" section.)
PAGE CNT PRINT	PAGE CNT PRINT	ENABLE DISABLE	*	Sets printing or not printing the total page count in PRINT MENU MAP.
PERSONALITY	PCL	ENABLE DISABLE	*	Change the default PDL for each brand. PDLs that are disabled in this Menu will not be displayed on User Menu or Adomin Menu's PERSONALITY.
	IBM PPR III XL	ENABLE DISABLE	*	When print data in the PDL language set to DISABLE is received, the printer will display INVALID DATA and discard received data. (HP-GL/2 is under development, and there is no plan
	EPSON FX	ENABLE DISABLE	*	to implement as yet in the product.) The PDF function requires Adobe Postscript;
	Adobe Postscript	ENABLE DISABLE	*	thus, switching ON/OFF of PDF alone is disabled.
	HP-GL/2	ENABLE DISABLE	*	(Setting Adobe Postscript on DISABLE will set the PDF function to DISABLE as well.)
	PCL XL	ENABLE DISABLE	*	On the PX711/713, neither Adobe Postscript nor PDF can be set to DISABLE. (They are to be always set to ENABLE for use. Even if they are
	PDF	ENABLE DISABLE	*	set to DISABLE, the printer processes the data it receives. This item is incorporated only in the menu ahead of time for future extension.)

Table 3-0 (2/2) Maintenance Menu display Table

Category	Item(1st Line)	Value(2nd Line)	DF	Functions
NETWORK				The details depend on Network. (Not used)
DIAGNOSTIC MODE XX.XX.XX				Enters engine self-diagnostic mode. The display in place of xx.xx varies among the PU version. (The disply within this category depends on the Engine Maintenance specs.)

Switch operations and LCD displays in Engine Self-diagnostic Mode depend on the instructions from the Engine F/W; hence, they are different from the operation spec in the Controller F/W.
Engine Self-diagnostic Mode is excutable even if the Controller board is removed.

For details, see the Engine Unit spec as needed.

3.0.1   ID Check Pattern Printing (" TEST PRINT MENU " item)

This pattern can be used for the cause investigation (specifying of color(C,M,Y,K) of the problem item, the confirmation of the periodicity) of the following problem that it originated in ID, the LED head. It is composed of CMYK color 20% duty each of the patterns (print 2 pages).
      Operation: (Press switch)
          Without HDD: "0" - "0" - "3" - "3"
          With HDD   : "0" - "0" - "0" - "3" - "3"

          - Vertical Black/White Lines
          - Vertical Black/White Bands
          - Horizontal Black/White Lines
          - Horizontal Black/White Bands

Print pattern: Page.1   Page.2

3.1   Maintenance Mode and Functions
3.1.1   Maintenance menu

A maintenance menu category is located in the general menu category.
The following items are those that can be set with this menu.

Maintenance Menu

Category	Item(1st Line)	Value(2nd Line)	DF	Functions
MAINTENANCE MENU	EEPROM reset	EXECUTE	*	Resets EEPROM for CU.
	SAVE MENU Save menu setting	EXECUTE	*	Saves current menu setting. A message asking Are you sure? and a choice of YES/NO will appear.
	RESTORE MENU Return to saved menu setting	EXECUTE	*	Changes setting to the stored menu setting. (Displayed only when a menu setting is stored.) *NOTE*: Stored in CU Flash (directly attached). In HDD if HDD exists.
	POWER SAVE Power save function	Enabled Disabled	*	Enables or disables the power save mode. The time to switch to Power Save Enable can be changed with the Power Save Delay Time Item in the System Configuration Menu.
	Normal paper black setting	0 +1 +2 -2 -1	*	Normal Paper/Black Print Used for fine adjustment when scratches or dots are notable on print results. Decrement if the highly-dense print portion seems dispersed or scattered with white dust. Increment if the print result seems faint.
	Normal paper color setting	0 +1 +2 -2 -1	*	Normal Paper/Color Print Used for fine adjustment when scratches or dots are notable on print results. Decrement if the highly-dense print portion seems dispersed or scattered with white dust. Increment if the print result seems faint.
	OHP paper black setting	0 +1 +2 -2 -1	*	OHP/Black Print Used for fine adjustment when scratches or dots are notable on print results. Decrement if the highly-dense print portion seems dispersed or scattered with white dust. Increment if the print result seems faint.
	OHP paper color setting	0 +1 +2 -2 -1	*	OHP/Color Print Used for fine adjustment when scratches or dots are notable on print results. Decrement if the highly-dense print portion seems dispersed or scattered with white dust. Increment if the print result seems faint.

3.1.2   Engine maintenance mode

Three modes from Level 1 to Level 3 are in the engine maintenance mode. Level 1 is a mode that checks the media transport and basic movement of the print system. Level 2 checks the counter for consumables and tests the correcting function of color displacement, and is a mode that does not require special knowledge. Level 3, on the other hand, requires special knowledge for handling the process parameter setting and is contained in the independent experimental element of PU. Basically, levels other than Level 1 should not be used.

3.1.2.1 Operator panel

The description for operations related to self-diagnosis is made presuming the arrangement of the operator panel shown below.

3.1.2.2 General self-diagnostic mode (Level 1)

Items in the normal self-diagnostic mode menu are listed below.
• Switch scan test
• Motor & clutch test
• Executing test pattern
• NVM initialization
• Consumables counter display
• Consumables continuation counter display

ATTENTION

3.1.2.2.1   Entering self-diagnostic mode (Level 1)

1. The system maintenance menu mode is entered by turning the power ON while pressing the ⓪, ①,⑥, and ⑦ keys simultaneously.
2. Press the ⓪ key several times until [DIAGNOSTIC MODE] is displayed.

```
DIAGNOSTIC MODE

XX.XX.XX          FACTORY/SHIPPING
```

3. The [XX.XX.XX] in [DISGNOSTIC MODE XX.XX.XX] that is displayed in the LCD display is the ROM version. The set value for FACTORY WORKING MODE is displayed in the right side of the bottom line. [SHIPPING] is normally set.
4. Proceed to each self-diagnosis step by pressing the ① or ⑤ key.
   (The menu item rotates by pressing the ①,⑤ key.)

3.1.2.2.2   Exiting self-diagnostic mode

1. Turn the power OFF, then turn it on after ten seconds.

3.1.2.3 Switch scan test

This self-diagnosis is used for checking the input sensor and switch.

1. Press the ① and ⑤ keys until the normal diagnostic mode is entered and [SWITCH SCAN] is displayed on the top line.
   (Key ① increments the test item and Key ⑤ decrements the test item.)

```
SWITCH SCAN


```

2. Press the ② and ⑥ keys until the SCAN number that corresponds to the unit subject to the following test listed in Table 3-1. (Key ② increments the item and Key ⑥ decrements the item.)

```
SWITCH SCAN 00

1=H 2=L 3=H 4=L
```

3. The test starts by pressing the ③ key. The SWITCH SCAN number begins to blink and the number of the corresponding unit (1-4) is displayed along with the current status.
   Manipulate each unit (Fig 3-1). The items are displayed in the LCD that corresponds to each item. (The display differs for each sensor. See Table 3-1 for details.)
4. The SWITCH SCAN number reappears in the display status (blinking ceased) by pressing the ⑦ key.
5. Repeat Steps 2 to 4 as required.
6. Press the ④ key to end the test. (Status returns to that described in 1.)

Stacker full sensor

Job offset sensor

Job offset home sensor

Left cover switch

Face up sensor

Paper eject sensor

Color irregularity sensor (L)
Color irregularity sensor (R)
Density sensor

Duplex print entrance sensor

Duplex print left sensor

Cassette 1 paper size switch

Cassete 2 paper size switch

Cassette 3 paper size switch

Cassette 4 paper size switch

Cassete 5 paper size switch

Top fuser sensor
(center/left)

Bottom fuser sensor
(center)

C toner sensor

M toner sensor

Y toner sensor

K toner sensor

Cover up switch

Heat/Humidity sensor

Paper weight sensor

OHP sensor

Paper empty sensor

MT home switch

Entrance MT sensor

Entrance belt sensor

Belt waste toner sensor

Entrance cassette sensor

Duplex print right sensor

Hopping sensor

Cover right switch

Lift up switch

Paper empty sensor

Carier sensor

Paper near sensor

Cassette 2 hopping sensor
Cassette 2 cover front switch
Cassette 2 lift up switch
Cassette 2 paper empty sensor
Cassette 2 carier sensor
Cassette 2 paper near sensor

Cassette 3 hopping sensor
Cassette 3 cover front switch
Cassette 3 lift up sensor
Cassette 3 paper empty sensor
Cassette 3 carier sensor
Cassette 3 paper near sensor

Cassette 4 hopping sensor
Cassette 4 cover front switch
Cassette 4 lift up sensor
Cassette 4 paper empty sensor
Cassette 4 carier sensor
Cassette 4 paper near sensor

Cassette 5 hopping sensor
Cassette 5 cover front switch
Cassette 5 lift up sensor
Cassette 5 paper empty sensor
Cassette 5 carier sensor
Cassette 5 paper near sensorT

Figure 3-1 Switch Sensor Position

Table 3-1 SWITCH SCAN Details

SCAN ROW	NUMBER							
	1	Display	2	Display	3	Display	4	Display
SWITCH SCAN 00	Cassette 1 paper end sensor	Port level H,L	Cassette 1 paper near end sensor	Port level H,L	Entrance cassette sensor	Port level H,L	Entrance MT sensor	Port level H,L
SWITCH SCAN 01	Entrance belt sensor	Port level H,L	Eject sensor	Port level H,L	Stacker full sensor	Port level H,L	Belt waste toner	Port level H,L
SWITCH SCAN 02	K toner sensor	Port level H,L	C toner sensor	Port level H,L	M toner sensor	Port level H,L	Y toner sensor	Port level H,L
SWITCH SCAN 03	Upper cover SW	Port level H,L	Front cover SW	Port level H,L	-	-	-	-
SWITCH SCAN 04	-	-	-	-	-	-	-	-
SWITCH SCAN 05	-	-	-	-	-	-	-	-
SWITCH SCAN 06	MT hop switch	Port level H,L	MT paper empty SW	Port level H,L	-	-	OHP sensor	Port level H,L
SWITCH SCAN 07 (See Table 4-2)	Cassette 1 paper size SW	Port level H,L	Cassette 1 paper size 2 SW	Port level H,L	Cassette 1 paper size 3 SW	Port level H,L	Cassette 1 paper size 4 SW	Port level H,L
SWITCH SCAN 08	Color irregularity sensor	AD value ***H	Color displacement sensor (R)	AD value ***H	Density sensor	AD value ***H	Paper weight sensor	AD value ***H
SWITCH SCAN 09	Center sensor above fuser	AD value ***H	-	-	Center sensor below fuser	-	-	-
SWITCH SCAN 10	Humidity sensor	AD value ***H	Temperature sensor	AD value ***H	-	-	-	-
SWITCH SCAN 11 (Option)	Duplex print entrance sensor	Port level H,L	Duplex print rear sensor	Port level H,L	-	-	Duplex print front sensor	Port level H,L
SWITCH SCAN 12 (Option)	Cassette 2 paper size 1 SW	Port level H,L	Cassette 2 paper size 2 SW	Port level H,L	Cassette 2 paper size 3 SW	Port level H,L	Cassette 2 paper size 4 SW	Port level H,L
SWITCH SCAN 13 (Option)	Cassette 2 paper empty sensor	Port level H,L	Cassette paper near end sensor	Port level H,L	-	-	-	-
SWITCH SCAN 14 (Option)	-	-	-	-	Cassette 2 hopping sensor (paper feed)	Port level H,L	-	-
SWITCH SCAN 15 (Option)	Cassette 3 paper size 1 SW	Port level H,L	Cassette 3 paper size 2 SW	Port level H,L	Cassette 3 paper size 3 SW	Port level H,L	Cassette 3 paper size 4 SW	Port level H,L
SWITCH SCAN 16 (Option)	Cassette 3 paper empty sensor	Port level H,L	Cassette 3 paper near end sensor	Port level H,L	-	-	-	-
SWITCH SCAN 17 (Option)	-	-	-	-	Cassette 3 hopping sensor (paper feed)	Port level H,L	-	-
SWITCH SCAN 24	Black head temperature	AD value ***H	Yellow head temperature	AD value ***H	Magenta head temperature	AD value ***H	Cyan head temperature	AD value ***H
SWITCH SCAN 25	Black ID up/down sensor	Port level H,L	Yellow ID up/down sensor	Port level H,L	Magenta ID up/down sensor	Port level H,L	Cyan ID up/down sensor	Port level H,L

Table 3-2 Paper Size Detection - Paper /Bit Correspondence Table

No.	Paper	1	2	3	4
[0]	No cassette	H	H	H	H
[1]	Letter-S	L	L	L	L
[2]	Legal13-S	H	L	H	H
[3]	A4-S	L	L	L	H
[4]	B5-S	L	L	H	H
[5]	Executive-S	L	L	H	L
[6]	A6-S	H	L	L	L
[7]	Not supported	—	—	—	—
[8]	Legal14-S	H	L	H	L
[9]	Not supported	—	—	—	—
[A]	Not supported	—	—	—	—
[B]	Not supported	—	—	—	—
[C]	A5-S	H	L	L	H
[D]	Not supported	—	—	—	—
[E]	Not supported	—	—	—	—
[F]	Not supported	—	—	—	—

3.1.2.4 Motor clutch test

This self-diagnostic routine is used to test the motor and clutch.

1. Press the ① and ⑤ keys until the self-diagnostic (Level 1) mode is entered and [MOTOR & CLUTCH TEST] is displayed in the top line.(Key ① increments the test item and Key ⑤ decrements the test item.)
2. Press the ② and ⑥ keys until the section that corresponds to the unit subject to the next test in Table 3-2 is displayed in the top line of the display. (Key ② increments the item and Key ⑥ decrements the item.)

```
MOTOR & CLUTCH TEST

BLACK - ID MOTOR
```

3. The test starts by pressing the ③ key. The name of the unit begins to blink and the corresponding unit drives for 10 seconds. (See Fig 3-3.)

Note: The status returns to that described in 2 after driving 10 seconds, and the unit will start driving again be pressing the corresponding switch.

- The drive control conditions listed in Table 3-2 must be fulfilled in order to drive the corresponding unit. A unit cannot be driven without fulfilling the conditions, and if attempted, instructions will appear in the bottom display line.
- For clutch solenoid, ON and OFF is repeated for normal print drive. (For those that cannot be driven independently due to their mechanism, drive with the motor.)

4. A driving unit is stopped by pressing the ⑦ key. (The display of the corresponding unit is maintained.)
5. Repeat Steps 2 to 4 as required.
6. Press the ④ key to end the test. (Status returns to that described in 1.)

Figure 3-3

Table 3-2

Displayed Unit	Drive Restrictions	Restriction Display
ID motor (black)	Drive by removing all ID (yellow/black/magenta/cyan).	Remove ID
ID motor (yellow)		
ID motor (magenta)		
ID motor (cyan)		
Belt motor		
Fuser motor	-	-
Resist motor	-	-
Job offset motor	-	-
Cassette 1 motor	Drive by removing Cassette 1.	Remove Cassette 1
Lift up motor	-	-
Resist clutch	-	-
Sensor shutter solenoid	-	-
Eject solenoid	-	-
Feed clutch	-	-
Carrier clutch	-	-
Duplex print motor (option)	-	-
Duplex print solenoid (option)	-	-
Duplex print left clutch (option)	-	-
Duplex print right clutch (option)	-	-
Cassette 2 motor (option)	Drive by removing Cassette 2.	Remove Cassette 2
Cassette 2 lift up motor (option)	-	-
Cassette 2 feed clutch (option)	-	-
Cassette 2 carrier clutch (option)	-	-
Cassette 3 motor (option)	Drive by removing Cassette 3.	Remove Cassette 3
Cassette 3 lift up motor (option)	-	-
Cassette 3 feed clutch (option)	-	-
Cassette 3 carrier clutch (option)	-	-
Cassette 4 motor (option)	Drive by removing Cassette 4.	Remove Cassette 4
Cassette 4 lift up motor (option)	-	-
Cassette 4 feed clutch (option)	-	-
Cassette 4 carrier clutch (option)	-	-
Cassette 5 motor (option)	Drive by removing Cassette 5.	Remove Cassette 5
Cassette 5 lift up motor (option)	-	-
Cassette 5 feed clutch (option)	-	-
Cassette 5 carrier clutch (option)	-	-
ID UP/DOWN	-	-
FAN1 TEST (Power Source Fan)	-	-
FAN2 TEST (Control Unit Fan)	-	-

3.1.2.5 Test print

This self-diagnostic routine is used to print the test patterns in the PU. The other test patterns are stored in the controller.

1. Press the ① and ⑤ keys until the self-diagnostic (Level 1) mode is entered and [TEST PRINT] is displayed in the top line. (Key ① increments the test item and Key ⑤ decrements the test item.)
2. The bottom line displays the setup items applied only for test print. Press the ② and ⑥ keys until the corresponding item is displayed. (Key ② increments the item and Key ⑥ decrements the item.)
3. When the ③ and ⑦ keys are pressed, the setup items appear in the top line and set values appear in the bottom line. The set value increments by pressing the ③ key and decrements by pressing the ⑦ key. (The value that is set at the end will be applied.) Repeat Stop 3 as required.

```
TEST PATTERN

1
```

Display	Set Value	Function
PRINT EXECUTE	—	Press Key ③ to start print. / Press Key ⑦ to end print. (In page unit.)
TEST PATTERN	0	0: empty page 1-7: Refer to the following page (pattern print). 8-15: empty page
CASSET	TRAY1	Set paper feed source.
	TRAY2	
	TRAY3	
	FF	
PAGE	0000	Set number of pages to test print.
COLOR	ON	Select color or monochrome.
	OFF	
DUPLEX	2 PAGES STACK	Perform duplex print with 2-page stack.
	OFF	Set duplex print to OFF.
	1PAGES STACK	Perform duplex print with 1-page stack.

- ☐ is the default. The set items are valid only in this test mode. (They will not be written in EEPROM.)

Note: Page setting: Key ① or ⑤ shifts the digits.
Color setting: The following indications appear in the panel when Key ① or ⑤ is pressed when set to [ON].
Print setting for each color:
Shifts by pressing Key ① or ⑤.
Switch between [ON] and [OFF] is set by pressing Key ③ or ⑦.
Panel indication returns by pressing Key ② or ⑥.

```
COLOR

Y:ON M:ON C:ON K:ON
```

4. Test print will be executed under the values set in Steps 2 and 3 by pressing the ③ key when [PRINT EXECUTE] is displayed in the bottom row of the display.

Press the ⑦ key to stop the test print.

When an alarm indicated under Details in the table is detected at the start of test print or during test print, a message will appear in the panel display and the print operation will be interrupted. (Refer to "3.1.2.9 Panel display details" for details on errors.)

Print pattern
0, 8-15: Empty print

Pattern 1

Pattern 2

Pattern 3

Pattern 4

Pattern 5

Pattern 6

Pattern 7

• The following messages appear during print operation.

```
P=*** T=*** U=***[###]

H=***%        L=***[###]
```

P: No. of test print pages (unit: page)
U: Temperature of top heater [Set value] (unit: Celsius)
L: Temperature of bottom heater [Set value] (unit: Celsius)
T: Environment temperature (unit: Celsius)
H: Environment humidity (unit: percent)

• The display changes by pressing the ③ key.

```
KTR=*.**KV YTR=*.**KV

MTR=*.**KV CTR=*.**KV
```

YTR, MTR, CTR, KTR are values of the set transfer voltage. (unit: KV)

• The display changes by pressing the ③ key.

```
KR=*.**KV YR=*.**KV

MR=*.**KV CR=*.**KV
```

YR, MR, CR, KR are transfer rollers of each color values of the set transfer voltage. (unit: KV)

5. Repeat Steps 2 to 4 as required.
6. Press the ④ key to end the test. (Status returns to that described in 1.)

3.1.2.6 NVM initialization

This self-diagnosis is used for initializing non-volatile memory.

1. Press the ① and ⑤ keys until the self-diagnostic (Level 1) mode is entered and [NV-RAM INITIAL] is displayed in the top line. (Key ① increments the item and Key ⑤ decrements the item.)
2. The bottom line displays the table number subject to initialization. There are three tables to initialize. Press the ② and ⑥ keys until the corresponding table number is displayed. (Key ② increments the table number and Key ⑥ decrements the table number.)

```
NV-RAM INITIAL

TABLE 1
```

Note: Do not use Table 2.

3. The [NV-RAM INITIAL] display blinks when the ③ key is pressed and all items in Table 3-3 will be initialized by pressing the key for 10 seconds continuously.
4. Press the ④ key to end the test. (Status returns to that described in 1.)

Table 3-3 (1/2) Items to Initialize in Table 2

Item to Initialize		Details	Initial Value	Unit
Drum counter	Black Yellow Magenta Cyan	Initialize internal counter since exchanging the drum.	0	-
Belt unit counter		Initialize internal counter since exchanging the belt unit.	0	-
Fuser unit counter		Initialize internal counter since exchanging the fuser unit.	0	-
Toner counter	Black Yellow Magenta Cyan	Initialize internal counter since recovering the toner error.	0	-

Table 3-3 (2/2) Items to Initialize in Table 2

Item to Initialize		Details	Initial Value	Unit
Color irregularity adjust point X axis	Yellow Magenta Cyan	Initialize X axis correction value for the LED head (yellow, magenta, cyan).	0	1/1200 inch
Color irregularity adjust point Y axis (L)	Yellow Magenta Cyan	Initialize Y axis (L) correction value for the LED head (yellow, magenta, cyan).	0	1/1200 inch
Color irregularity adjust point Y axis (R)	Yellow Magenta Cyan	Initialize Y axis (R) correction value for the LED head (yellow, magenta, cyan).	0	1/1200 inch
Engine parameter		Initialize all items set in Level 2 and 3 in the engine maintenance mode.		

3.1.2.7 Consumable counter display

This self-diagnosis is used for displaying the consumed status of consumables.

1. Press the ① and ⑤ keys until the normal self-diagnostic mode is entered and [CONSUMABLE STATUS] is displayed in the top line. (Key ① increments the item and Key ⑤ decrements the item.)
2. The consumed status of consumables is displayed by pressing the ② and ⑥ keys. (Keys ③ and ⑦ are invalid.)
3. Press the ④ key to end the test. (Status returns to that described in 1.)

Item	Top Display	Bottom Display	Format	Unit	Details
Fuser unit	FUSER UNIT	******** PRINTS	Decimal system	Printed sheets	Displays number of pages since installing a new fuser.
Belt unit	TR BELT UNIT	******** PRINTS	Decimal system	Printed sheets	Displays number of pages since installing a new drum unit.
ID unit - black	BLACK ID UNIT	******** IMAGES	Decimal system	Printed sheets	Displays number of rotations by converting to A4 3Page/Job since installing a new ID unit.
ID unit - yellow	YELLOW ID UNIT	******** IMAGES	Decimal system	Printed sheets	
ID unit - magenta	MAGENTA ID UNIT	******** IMAGES	Decimal system	Printed sheets	
ID unit - cyan	CYAN ID UNIT	******** IMAGES	Decimal system	Printed sheets	
Toner - black	BLACK TONER	***%	Decimal system	%	Displays amount of color toner used.
Toner - yellow	YELLOW TONER	***%	Decimal system	%	
Toner - magenta	MAGENTA TONER	***%	Decimal system	%	
Toner - cyan	CYAN TONER	***%	Decimal system	%	

3.1.2.8 Consumable counter display - continuous

This self-diagnosis is used for displaying the continuous status of a consumable.
Continuous status of a consumable is the total count of a consumable that is not initialized even upon being replaced. The consumed amount is counted continuously.

1. Press the ① and ⑤ keys until the normal self-diagnostic mode is entered and the continuous status of a consumable is displayed in the top line. (Key ① increments the item and Key ⑤ decrements the item.)
2. The total consumed amount of a consumable is displayed by pressing the ② and ⑥ keys. (Keys ③ and ⑦ are invalid.)
3. Press the ④ key to end the test. (Status returns to that described in 1.)

Item	Top Display	Bottom Display	Format	Unit	Details
Total sheets feed	TOTAL SHEETS FEED	******** PRINTS	Decimal system	Printed sheets	Total number of fed sheets including passed paper.
Print - black	BLACK IMPRESSIONS	******** IMAGES	Decimal system	Printed sheets	Displays number of printed sheets for each color ID.
Print - yellow	YELLOW IMPRESSIONS	******** IMAGES	Decimal system	Printed sheets	
Print - magenta	MAGENTA IMPRESSIONS	******** IMAGES	Decimal system	Printed sheets	
Print - cyan	CYAN IMPRESSIONS	******** IMAGES	Decimal system	Printed sheets	

3.1.2.9 Error Messages and their details

Panel display

Panel Display	Details
BLANCE ERROR	Balance error
BELT LIFE OVER	Belt life over
BELT REFLECTION ERROR	Belt reflection error
BELT UNIT FUSE CUT ERROR	Belt unit fuse cut error
BLACK DENSITY CALIB ERROR	Black density calibration error
BLACK DENSITY SENSOR ERROR	Black density sensor error
BLACK DRUM LIFE OVER	Black drum life over
BLACK DRUM NEAR LIFE	Black drum life warning
BLACK DRUM UNIT FUSE CUT ERROR	Black drum unit fuse cut error
BLACK DRUM UP/DOWN ERROR	Black drum up/down error
BLACK IRREGULAR ERROR	Black detect range out error
BLACK LED HEAD ERROR	Black LED head error
BLACK REGISTRATION ERROR(PX711)	Black irregularity error
BLACK REGISTRATION OUT HORIZONTAL	Abnormal color irregularity registration value detected in black sub-scan registration
BLACK REGISTRATION OUT LEFT	Black registration range out error (left)
BLACK REGISTRATION OUT RIGHT	Black registration range out error (right)
BLACK SENSOR ERROR LEFT	Black left sensor error
BLACK SENSOR ERROR RIGHT	Black right sensor error
BLACK TONER EMPTY	Black toner empty
BLACK TONER LOW	Black toner low
BLACK TONER SENSOR ERROR	Black toner sensor error
BLACK ID DENSITY ERROR 1	Black ID density error 1
BLACK ID DENSITY ERROR 2	Black ID density error 2
CALIBRATION CHIP ERROR	CALIBRATION CHIP ERROR
CALIBRATION ERROR	CALIBRATION ERROR
COLOR DENSITY CALIB ERROR	COLOR DENSITY CALIB ERROR
COLOR DENSITY SENSOR ERROR	COLOR DENSITY SENSOR ERROR
COOLING DOWN	COOLING DOWN
CUSTOM DIAGNOSTICS MODE	CUSTOM DIAGNOSTICS MODE
CYAN DRUM LIFE OVER	CYAN DRUM LIFE OVER
CYAN DRUM NEAR LIFE	CYAN DRUM NEAR LIFE
CYAN DRUM UNIT FUSE CUT ERROR	CYAN DRUM UNIT FUSE CUT ERROR
CYAN DRUM UP/DOWN ERROR	CYAN DRUM UP/DOWN ERROR
CYAN IRREGULAR ERROR	CYAN DETECT VALUE ERROR
CYAN LED HEAD ERROR	CYAN LED HEAD ERROR
CYAN REGISTRATION ERROR	CYAN COLOR IRREGULARITY ERROR
CYAN REGISTRATION OUT HORIZONTAL	Abnormal color irregularity registration value detected in cyan sub-scan registration
CYAN REGISTRATION OUT LEFT	CYAN REGISTRATION OUT LEFT
CYAN REGISTRATION OUT RIGHT	CYAN REGISTRATION OUT RIGHT
CYAN SENSOR ERROR LEFT	CYAN SENSOR ERROR LEFT
CYAN SENSOR ERROR RIGHT	CYAN SENSOR ERROR RIGHT
CYAN TONER EMPTY	CYAN TONER EMPTY
CYAN TONER LOW	CYAN TONER LOW
CYAN TONER SENSOR ERROR	CYAN TONER SENSOR ERROR
CYAN ID DENSITY ERROR 1	CYAN ID DENSITY ERROR 1
CYAN ID DENSITY ERROR 2	CYAN ID DENSITY ERROR 2
DIAGNOSTICS MODE	DIAGNOSTICS MODE
DISPOSAL TONER FULL	DISPOSAL TONER FULL
DISPOSAL TONER NEAR FULL	DISPOSAL TONER NEAR FULL

Panel Display	Details
DRIVE MOTOR OVER HEAT	DRIVE MOTOR OVER HEAT
DUPLEX I/F ERROR	DUPLEX I/F ERROR
DUPLEX TYPE MISMATCH	DUPLEX TYPE MISMATCH
DUPLEX UNIT OPEN(PX713)	DUPLEX UNIT OPEN(PX713)
ENGINE BOARD FAN MOTOR ERROR	ENGINE BOARD FAN MOTOR ERROR
ENGINE CONTROL ERROR	ENGINE CONTROL ERROR
ENGINE EEPROM ERROR	ENGINE EEPROM ERROR
ENGINE EEPROM MISSING	ENGINE EEPROM MISSING
ENGINE LIFE OVER	ENGINE LIFE OVER
ENGINE RAM ERROR	ENGINE RAM ERROR
ENGINE ROM ERROR	ENGINE ROM ERROR
ENGINE SRAM ERROR	ENGINE SRAM ERROR
ENV TEMP SENSOR ERROR	ENV TEMP SENSOR ERROR
FACE-UP STACKER OPEN	FACE-UP STACKER OPEN
FLASH HARDWARE ERROR	FLASH HARDWARE ERROR
FLASH SOFTWARE ERROR	FLASH SOFTWARE ERROR
FRONT COVER OPEN(PX711)	FRONT COVER OPEN(PX711)
FUSER LIFE OVER	FUSER LIFE OVER
FUSER UNIT FAN MOTOR ERROR	FUSER UNIT FAN MOTOR ERROR
FUSER UNIT FUSE CUT ERROR	FUSER UNIT FUSE CUT ERROR
FUSER UNIT MISMATCH	FUSER UNIT MISMATCH
HOPPING ERROR DUPLEX	HOPPING ERROR DUPLEX
HOPPING ERROR MULTI PURPOSE FEEDER	HOPPING ERROR MULTI PURPOSE FEEDER
HOPPING ERROR TRAY1	HOPPING ERROR TRAY1
HOPPING ERROR TRAY2	HOPPING ERROR TRAY2
HOPPING ERROR TRAY3	HOPPING ERROR TRAY3
HOPPING ERROR TRAY4	HOPPING ERROR TRAY4
HOPPING ERROR TRAY5	HOPPING ERROR TRAY5
HUMIDITY SENSOR DEW ERROR	HUMIDITY SENSOR DEW ERROR
HUMIDITY SENSOR ERROR	HUMIDITY SENSOR ERROR
INFEED:DUPLEX	Duplex hopping error
INFEED:MP-FEEDER	MP feeder hopping error
INFEED:TRAY1	Tray 1 hopping error
INFEED:TRAY2	Tray 2 hopping error
INFEED:TRAY3	Tray 3 hopping error
INFEED:TRAY4	Tray 4 hopping error
INFEED:TRAY5	Tray 5 hopping error
INITIALIZING	Controlling initialization upon power ON
INITIALIZING	Controlling initialization upon cover open/close
INITIALIZING DENSITY ADJUST	Controlling adjustment of auto density
INITIALIZING REGISTRATION ADJUST	Controlling adjustment of auto color irregularity
INPATH:DUPLEX ENTRY	Duplex internal jam
INPATH:DUPLEX INPUT	Duplex transport jam
INPATH:DUPLEX REVERSAL	Duplex reversal unit jam
INPATH:EXIT	Ejection jam
INPATH:FEED	Feed jam
INPATH:TRANSPORT	Transport jam
JAM DUPLEX ENTRY	Duplex internal jam
JAM DUPLEX INPUT	Duplex transport jam
JAM DUPLEX REVERSAL	Duplex reversal unit jam
JAM EXIT	Ejection jam
JAM FEED	Feed jam

Panel Display	Details
JAM TRANSPORT	Transport jam
JOB OFFSET HOME ERROR(PX713)	JOB OFFSET HOME ERROR(PX713)
LED HEAD OVER HEAT	LED HEAD OVER HEAT
LIFT ERROR TRAY1(PX713)	LIFT ERROR TRAY1(PX713)
LIFT ERROR TRAY2(PX713)	LIFT ERROR TRAY2(PX713)
LIFT ERROR TRAY3(PX713)	LIFT ERROR TRAY3(PX713)
LIFT ERROR TRAY4(PX713)	LIFT ERROR TRAY4(PX713)
LIFT ERROR TRAY5(PX713)	LIFT ERROR TRAY5(PX713)
LIFT UP TRAY1(PX713)	LIFT UP TRAY1(PX713)
LIFT UP TRAY2(PX713)	LIFT UP TRAY2(PX713)
LIFT UP TRAY3(PX713)	LIFT UP TRAY3(PX713)
LIFT UP TRAY4(PX713)	LIFT UP TRAY4(PX713)
LIFT UP TRAY5(PX713)	LIFT UP TRAY5(PX713)
LOWER HEATER HIGH TEMPER	LOWER HEATER HIGH TEMPER
LOWER HEATER LOW TEMPER	LOWER HEATER LOW TEMPER
LOWER HEATER OPEN ERROR	LOWER HEATER OPEN ERROR
LOWER HEATER SHORT ERROR	LOWER HEATER SHORT ERROR
MAGENTA DRUM LIFE OVER	MAGENTA DRUM LIFE OVER
MAGENTA DRUM NEAR LIFE	MAGENTA DRUM NEAR LIFE
MAGENTA DRUM UNIT FUSE CUT ERROR	MAGENTA DRUM UNIT FUSE CUT ERROR
MAGENTA DRUM UP/DOWN ERROR	MAGENTA DRUM UP/DOWN ERROR
MAGENTA IRREGULAR ERROR	MAGENTA IRREGULAR ERROR
MAGENTA LED HEAD ERROR	MAGENTA LED HEAD ERROR
MAGENTA REGISTRATION ERROR	MAGENTA REGISTRATION ERROR
MAGENTA REGISTRATION OUT HORIZONTAL	Abnormal color irregularity registration value detected in magenta sub-scan registration
MAGENTA REGISTRATION OUT LEFT	MAGENTA REGISTRATION OUT LEFT
MAGENTA REGISTRATION OUT RIGHT	MAGENTA REGISTRATION OUT RIGHT
MAGENTA SENSOR ERROR LEFT	MAGENTA SENSOR ERROR LEFT
MAGENTA SENSOR ERROR RIGHT	MAGENTA SENSOR ERROR RIGHT
MAGENTA TONER EMPTY	MAGENTA TONER EMPTY
MAGENTA TONER LOW	MAGENTA TONER LOW
MAGENTA TONER SENSOR ERROR	MAGENTA TONER SENSOR ERROR
MAGENTA ID DENSITY ERROR 1	MAGENTA ID DENSITY ERROR 1
MAGENTA ID DENSITY ERROR 2	MAGENTA ID DENSITY ERROR 2
MAILBOX I/F ERROR(PX711)	MAILBOX I/F ERROR(PX711)
MISSING BELT UNIT	MISSING BELT UNIT
MISSING BLACK DRUM	MISSING BLACK DRUM
MISSING CYAN DRUM	MISSING CYAN DRUM
MISSING FUSER UNIT	MISSING FUSER UNIT
MISSING MAGENTA DRUM	MISSING MAGENTA DRUM
MISSING YELLOW DRUM	MISSING YELLOW DRUM
MULTI PURPOSE FEEDER STAGE POSITION	MULTI PURPOSE FEEDER STAGE POSITION
PAPER END MULTI PURPOSE FEEDER	PAPER END MULTI PURPOSE FEEDER
PAPER END TRAY1	PAPER END TRAY1
PAPER END TRAY2	PAPER END TRAY2
PAPER END TRAY3	PAPER END TRAY3
PAPER END TRAY4	PAPER END TRAY4
PAPER END TRAY5	PAPER END TRAY5
PAPER NEAR END MULTI PURPOSE FEEDER	PAPER NEAR END MULTI PURPOSE FEEDER
PAPER NEAR END TRAY1	PAPER NEAR END TRAY1
PAPER NEAR END TRAY2	PAPER NEAR END TRAY2
PAPER NEAR END TRAY3	PAPER NEAR END TRAY3

Panel Display	Details
PAPER NEAR END TRAY4	PAPER NEAR END TRAY4
PAPER NEAR END TRAY5	PAPER NEAR END TRAY5
PAPER PILE OUT OF TRAY	Paper transport error
PAPER SIZE ERROR	PAPER SIZE ERROR
POWER SUPPLY FAN MOTOR ERROR	PU fan motor error
POWER SUPPLY LSI ERROR	POWER SUPPLY LSI ERROR
PROCESS CONTROL OFF	PROCESS CONTROL OFF
PROCESS WAIT MODE	Adjusting color irregularity / density (upon starting from CU)
PUNCH BOX NOT EXISTING(PX713)	PUNCH BOX NOT EXISTING(PX713)
PUNCH DUST OVERFLOW(PX713)	PUNCH DUST OVERFLOW(PX713)
REGISTRATION SENSOR CALIBRATION ERROR	REGISTRATION SENSOR CALIBRATION ERROR
R-SIDE COVER OPEN(PX713)	R-SIDE COVER OPEN(PX713)
SHUTTER ERROR1	Density adjustment shutter error 1
SHUTTER ERROR2	Density adjustment shutter error 2
STACKER FULL BOTTOM BIN(PX713)	STACKER FULL BOTTOM BIN(PX713)
STACKER FULL FACE DOWN	STACKER FULL FACE DOWN
STACKER FULL MAIL BOX1(PX711)	STACKER FULL MAIL BOX1(PX711)
STACKER FULL MAIL BOX2(PX711)	STACKER FULL MAIL BOX2(PX711)
STACKER FULL TOP BIN(PX713)	STACKER FULL TOP BIN(PX713)
THICKNESS ADJSTING	THICKNESS ADJSTING
THICKNESS NON-PAPER AD ERROR	AD out of regulated value error (upon no media)
THICKNESS PAPER THICKNESS ERROR	Media thickness out of range error
THICKNESS SNS AD ERROR	Sensor output difference out of range error (upon no media)
THICKNESS THICK_PAPER ERROR	Speed adjustment error
TOP COVER OPEN	TOP COVER OPEN
TRAY1 TYPE MISMATCH	TRAY1 TYPE MISMATCH
TRAY2 COVER OPEN(PX713)	TRAY2 COVER OPEN(PX713)
TRAY2 I/F ERROR	TRAY2 I/F ERROR
TRAY2 TYPE MISMATCH	TRAY2 TYPE MISMATCH
TRAY3 COVER OPEN(PX713)	TRAY3 COVER OPEN(PX713)
TRAY3 I/F ERROR	TRAY3 I/F ERROR
TRAY3 TYPE MISMATCH	TRAY3 TYPE MISMATCH
TRAY4 COVER OPEN(PX713)	TRAY4 COVER OPEN(PX713)
TRAY4 I/F ERROR	TRAY4 I/F ERROR
TRAY4 TYPE MISMATCH	TRAY4 TYPE MISMATCH
TRAY5 COVER OPEN(PX713)	TRAY5 COVER OPEN(PX713)
TRAY5 I/F ERROR	TRAY5 I/F ERROR
TRAY5 TYPE MISMATCH	TRAY5 TYPE MISMATCH
UPPER HEATER HIGH TEMPER	UPPER HEATER HIGH TEMPER
UPPER HEATER LOW TEMPER	UPPER HEATER LOW TEMPER
UPPER HEATER OPEN ERROR	UPPER HEATER OPEN ERROR
UPPER HEATER SHORT ERROR	UPPER HEATER SHORT ERROR
WARMING UP	WARMING UP
YELLOW DRUM LIFE OVER	YELLOW DRUM LIFE OVER
YELLOW DRUM NEAR LIFE	YELLOW DRUM NEAR LIFE
YELLOW DRUM UNIT FUSE CUT ERROR	YELLOW DRUM UNIT FUSE CUT ERROR
YELLOW DRUM UP/DOWN ERROR	YELLOW DRUM UP/DOWN ERROR
YELLOW IRREGULAR ERROR	YELLOW IRREGULAR ERROR
YELLOW LED HEAD ERROR	YELLOW LED HEAD ERROR
YELLOW REGISTRATION ERROR	YELLOW REGISTRATION ERROR
YELLOW REGISTRATION OUT HORIZONTAL	Abnormal color irregularity registration value detected in magenta sub-scan registration
YELLOW REGISTRATION OUT LEFT	YELLOW REGISTRATION OUT LEFT

Panel Display	Details
CYAN REGISTRATION OUT RIGHT	CYAN REGISTRATION OUT RIGHT
CYAN SENSOR ERROR LEFT	CYAN SENSOR ERROR LEFT
CYAN SENSOR ERROR RIGHT	CYAN SENSOR ERROR RIGHT
CYAN TONER EMPTY	CYAN TONER EMPTY
CYAN TONER LOW	CYAN TONER LOW
CYAN TONER SENSOR ERROR	CYAN TONER SENSOR ERROR
CYAN ID DENSITY ERROR 1	CYAN ID DENSITY ERROR 1
CYAN ID DENSITY ERROR 2	CYAN ID DENSITY ERROR 2

Details of jam error display

Panel Display	Details
INFEED:TRAY1	Tray 1 hopping error
INFEED:TRAY2	Tray 2 hopping error
INFEED:TRAY3	Tray 3 hopping error
INFEED:TRAY4	Tray 4 hopping error
INFEED:TRAY5	Tray 5 hopping error
INFEED:MP-FEEDER	MP feeder hopping error
INFEED:DUPLEX	Duplex hopping error
INPATH:DUPLEX INPUT	Duplex transport jam
INPATH:DUPLEX ENTRY	Duplex internal jam
INPATH:REVERSAL	Duplex reversal unit jam
INPATH:FEED	Feed jam
INPATH:TRANSPORT	Transport jam
INPATH:EXIT	Ejection jam

INFEED: Data on paper remaining at paper feed slot.
INPATH: Data on paper remaining in paper path.

41956001TH Rev.3

3.1.3   Various print jobs with single printer unit attached with a controller

Menu map print
    Prints program version, configuration of the control unit, and other printer configuration and setting.
    Operation: (Press switch)
    Without HDD   : "0" → "3" → "3"
    With HDD   : "0" → "0" → "3" → "3"

File list print
    Prints a file list stored in the HDD or Flash ROM.
    Operation: (Press switch)
    Without HDD   : "0" → "3" → "1" → "3"
    With HDD   : "0" → "0" → "3" → "1" → "3"

Font list print (PCL)
    Prints a font list for PCL.
    Operation: (Press switch)
    Without HDD   : "0" → "3" → "1" → "1" → "3"
    With HDD   : "0" → "0" → "3" → "1" → "1" → "3"

Font list print (PS)
    Prints a font list for PS.
    Operation: (Press switch)
    Without HDD   : "0" → "3" → "1" → "1" → "1" → "3"
    With HDD   : "0" → "0" → "3" → "1" → "1" → "1" → "3"

Demo print
    Prints a demo pattern for each subject installed in the ROM.
    Operation: (Press switch)
    Without HDD   : "0" → "3" → "1" → "1" → "1" → "1" → "3"
    With HDD   : "0" → "0" → "3" → "1" → "1" → "1" → "1" → "3"

Ethernet self-diagnostic print
    If an Ethernet board is installed, perform self-diagnosis by pressing the Ethernet board SW for two seconds or longer and print the result.

3.2 Adjustments after Parts Replacement

The following describes the adjustments that are required after replacing parts.
Adjustment and correction for color registration are always required for each part replacement.

Replaced Part	Adjustment
LED Head	Not required
Drum Cartridge (Y, M, C, K)	Not required.
Fuser Unit	Not required.
Belt Cassette Assy	Not required.
PU (K7N Board)	Re-mounting the EEPROM used on the board before replacement. *Note
CU (TIG board)	Re-mounting the EEPROM used on the board before replacement. *Note
Shutter	Setting the correction value of the calibration chip for detecting density.
Media Thickness Sensor Assy	Adjusting paper thickness detection sensitivity and checking media thickness detection value setting.

* Note:1. When the EEPROM of the PU (K7N board) is replaced to a new one, color balance must be adjusted.
* Note: 2. When the EEPROM of the CU (TIG board) is replaced to a new one, the Destination Setting must be adjusted.

3.2.1   Precautions in replacing engine control board

When replacing the engine control board (K7N PWB), remove the EEPROM from the old board and set it on a new board (for errors other than those of engine EEPROM).
When SERVICE CALL xxx (an engine EEPROM error) is displayed on the operator panel, the EEPROM must be replaced with new EEPROM. In this case, perform the operation described in section 3.2.2.

3.2.2   Precautions in replacing EEPROM

When the EEPROM is not removed from the board and placed on the new board at the time of engine controll board (K7N PWB) replacement, the Version Read function (fuse cut) is disabled.
The printer must be switched from the factory mode to the shipping mode by the PJL command.

[Description]
1. Sending of an appropriate PJL file to the printer to place it in Shipping mode
2. Sending of a repower-on or reboot command (PJL file) to complete the setting

[Procedure]
At the MS-DOS prompt, perform the following steps:
1. Enter Copy /b Pjl_ship.bin prn and hit <Enter>.
2. Enter Copy /b Pjl_reboot.bin prn and hit <Enter>, or power the printer off and on.

[Pjl Files Required]
1. Pjl-ship.bin
2. Pjl-reboot.bin

Note: Life data for consumables such as belt, toner, and ID is cleared when replacing EEPROM, therefore, be cautious as there will be a tolerance in life management upon replacing the unit in the future. The following count will be cleared when replacing EEPROM.
Other than Total Sheets Feed is cleared when each unit is replaced, therefore, the tolerance will be cleared at that point.

Item	Contents	Count
Fuser	Life count of the fuser	Value in which the number of printed pages is converted to the number of Letter paper after installing a new fuser unit.
Transfer Belt	Life count of the transfer belt	Value in which the number of printed pages is converted to the number of Letter paper after installing a new fuser unit.
Black Imaging Drum Cyan Imaging Drum Magenta Imaging Drum Yellow Imaging Drum	Life count of the imaging drums for each color	Value in which the number of rotations is converted to the number of Letter paper after installing a new ID unit.
Black Toner Cyan Toner Magenta Toner Yellow Toner	Count of the used toner amount for each color	Count of the number of printed dots.
Total Sheets Feed	Life count of the printer	Total number of printed pages.
Black Impressions Cyan Impressions Magenta Impressions Yellow Impressions	Total number of printed pages	Number of printed pages after installing a new ID unit.

3.2.3   EEPROM replacement after TIG board replacement

When replacing the TIG board, remove EEPROM from the board used by the user and set it to the replaced board. (This is to pass on the user set contents and font install data to the new board.) Furthermore, if the user's EEPROM cannot be used due to damages, use the EEPROM on the new board. In this case, the new board and EEPROM should be set with destinations.

3.2.4   Destination Setting (Checking Method: Printing Demo Page)

The destination setting of each main control board, which takes on ODA by default, must be set, at the time of printer shipment, to correspond to the destination of the printer equipped with the board.
Japan indirect sales, ODA, OEL and APS maintenance boards are to be shipped with the destination setting left at its default.

Setting on Operation Panel:
Powering up each printer in maintenance mode and then setting its destination are made.
While holding SWs ⓪, ①, ⑥, and ⑦ down, turn on printer.
After MAINTENANCE MENU is displayed on LCD, the display changes to OKIUSER.
Press SW ① to select OKIUSER for destination setting.
ODA   * appears on the lower display. Press SW ② to select a destination.
Confirm the setting by pressing SW ③.
Printer restarts, and comes up with the destination changed.

Description:
Each of Japan domestic and over seas ES3037/3037E uses a common ROM.
Destination setting must be made for the common ROM to be used in the printers to various destinations (the setting in the ROM default to ODA).
Setiings are stored in TIG board' s EEPROM.
Maintenance boards are to be shipped with the destination setting at its default and, when Settings are stored in TIG board' s EEPROM.

3.2.5   Recovery Flash ROM data on TIG board

A 4MB Flash ROM that enables a user to register an arbitrary file is installed on the TIG board.

Note: When a TIG board has to be replaced, print a file list of the information menu and check the registered files before replacing the board.
Re-register necessary files when the TIG board is replaced.

3.3   Adjusting the Density

The auto density adjust mode is set to [Auto] when the printer is delivered, however, problems may occur upon using the printer if the mode is set to [Manual]. Perform the procedure when the density is improper.

Note: Perform the task when the printer is not in operation. Do not perform during warm-up.

(1) Press ⓪ several times and display [Color Menu].
(2) Press ① or ⑤ and display [Density Adjust/Start].
(3) Press ③.

The auto density adjustment will begin.

3.4 Paper Thickness Detection Sensitivity Adjustment and Media Thickness Detection Value Check

Outline:

The sensitivity of a micro displacement sensor used for detecting media thickness varies from one to another. Therefore, to ascertain the sensitivity in advance, check the output value of the sensor by passing media of known thickness through the printer equipped with the sensor. The sensitivity is fixed based on the output value.

Adjustments must be made when the paper thickness sensor, the registration roller and the PU board are replaced.

By passing, from the multipurpose tray, four sheets of paper whose thickness has been measured with a micrometer (MDQ-30M, MDQ-30), the correction value for media thickness sensitivity is automatically set with the first three sheets. Check the media thickness detection value with the fourth sheet.

Media: Transparency (42404301)

Paper thickness difference: Within $\pm 10\mu m$

3.4.1 Applicable Operating Systems and Interfaces, and File Required

Software: AdjustmentMM.exe (Ver. 1.12)   File Required: Opusbase.dll

OS	I/F	File Type	File Name	Remarks
Win9x Series (95/98/Me)	Centronics	No file required	No file required	The interface port must be checked for its bidirectional setting.
	USB	USB driver	Oki USB Driver for Win98.exe	With the insertion of a USB, installation screen display is provided.
Win2000/XP	Centronics			Inapplicable
	USB	No file required	No file required	

Note: For use of a Centronics interface, the interface port must be checked for its bidirectional setting.

Checking: Check the parallel port is set to bidirectional in the BIOS setup (Parallel Mode parameter: Bi directional. No ECP/EEP).

Note: BIOS setup and program words vary with personal computers. Be sure to refer to the user documentation for the PC used.

(Example for NEC PCs)
(1) Power on the PC.
(2) POST (Power On Self-Test) details are displayed on the PC screen and then, at the lower left of the screen, Press <F2> to enter SETUP is shown.
(3) At the press of <F2>, SETUP is activated and the Main menu appears.
(4) Select Peripheral Configuration from the Advanced menu.
(5) Select Parallel Mode and check the parallel port is set to Bi directional.
(6) Press Esc to end the checking.

3.4.2   Setting

3.4.2.1 Menu Setting
 (1) Power on the PC.
 (2) Create an arbitrary folder, and copy the two files AdjustMM.exe and Opusbacc.dll into it
  (refer to the screen that is an example when the folder C:\MediaThickness has been created).

 (3) On the PC, activate the adjustment software AdjustMM (press OK on the screen that is
  provided only when the software is activated first time).

Perform steps (2) to (4) only in first-time menu setting.

 (4) Connect the printer AC cable and Centronics interface cable.

Note: • When a Centronics is used, operation is not performed unless the Centronics is set to bidirectional. Refer to 3.4.1 Applicable Operating Systems and Interfaces, and File Required.
  • When a USB is used with a Win9x series (Win95/98/Me), the USB driver "Oki USB Driver for Win98.exe" must be installed.

 (5) Power on the printer. Wait until the printer is placed on-line.
 (6) Mark the Config(C) checkbox and then press Setup Data.

(7) Setting screen appears. Select (mark) LPT1 or USB on the Printer Port menu. Press OK.

Note: Do not change settings other than those instructed here.

(8) The screen returns to the Adjust Munsell & Media screen. Press Media.

3.4.2.2 Media Setting

(1) The media thickness input screen is displayed.
Prepare four sensitivity adjustment transparency sheets (42404301) and enter the thicknesses with which the transparency sheets are labeled.

Input Data screen

Input Media-Thickness
Check data =

Input [100]

Four sensitivity Adjustment Transparency Sheets (42404301)

Transparency Sheet Appearance

PX713 Long Edge xxx μm
PX711 Short Edge xxx μm
DO NOT REUSE

Media Thickness Indication Label

Note: • Make thickness entries in μm (simply type in the value that is indicated on each transparency sheet). Enter the value of the long edge.
• Load the sheets in the multipurpose tray, in the order of their thickness entry (the media of the first entered thickness is to be lowermost in the multipurpose tray).

Thickness Entry Order	Screen Display	Tray Loading Order		Feed Order	Remarks
4	sample 1=	4	MP try top	1	Sensitivity adjustment 1st sheet
3	sample 2=	3		2	Sensitivity adjustment 2nd sheet
2	sample 3=	2		3	Sensitivity adjustment 3rd sheet
1	Check data=	1	MP try bottom	4	Check sheet

(2) After the completion of the thickness entry of the fourth sheet, the ADJUSTMM screen is shown.

ADJUSTMM screen

Set paper in the Printer .

Check data = 100
Sample 3 = 97
Sample 2 = 98
Sample 1 = 100

Start Adjustment Media-Thickness

Paper Orientation: Landscape

Measurement point

* Load four sheets of media so as that their measurement points are located at the front feeder - plate hopper.

3.4.2.3 Sensitivity Adjustment

(1) With the press of OK on the ADJUSTMM screen, sensitivity adjustment is performed. The printer boots up, and four sheets of media are passed through it.

```
ADJUSTMM                        [X]

  /!\   Set paper in the Printer .

        Check data  = 100
        Sample 3  =  97
        Sample 2  =  98
        Sample 1  = 100


        Start Adjustment Media-Thickness

        [  OK  ]      Cancel
```

(2) When the sensitivity adjustment is completed properly, the ADJUSTMM screen and the Adjust Munsell & Media screen are displayed.

```
ADJUSTMM                 [X]

  /!\   Adjustment GOOD

        [    OK    ]
```

```
Adjust Munsell & Media                          [X]

OKI | Adjustment Munsell-set & Media-thickness-calibration |

   Printer Number
   [                        ]              [   Exit   ]

        [ Execution  [Enter] ]             [ Version  ]

   Adjustment  GOOD                   |▼ Config (C)
   1033C  05 208A 1000011                [ Setup Data ]
   Media Thickness Adjustment
   Error Code = 0                        [   S / N   ]
   Thickness Check (Input)   = 100
   Thickness Check (Printer) = 98        [  Munsell  ]
   Thickness Calibration = -112  (4)
   Thickness D-1 = 100                   [   Media   ]
   Thickness D-2 = 98
   Thickness D-3 = 97                    [  Adj.Mode ]
   Thickness R-1 = 103
   Thickness R-2 = 98                    [  Online   ]
   Thickness R-3 = 101
   Medialess AD- 1 = 786                 [   Save    ]
   Medialess AD- 2 = 785
   Medialess AD- 3 = 786
   Medialess AD-Calb. = 786              [  Clear  ]
```

(3) When the sensitivity adjustment is not properly completed, the screen appears. In such cases, see Actions for NG Sensitivity Adjustment.

```
ADJUSTMM                                              [X]

  /!\   Failed to Send PJL to LPT1 !

        Err.Code : 1117 / The request could not be performed because of an I/O device error.

                        [    OK    ]
```

(4) The folder C:\MediaThickness is automatically created, storing the result of the sensitivity adjustment in the CSV format.
Determine cause(s) of NG results from the stored file. After the cause(s) are corrected, conduct sensitivity adjustment again.

```
Exploring - Media Thickness                                    _ □ X
 File  Edit  View  Go  Favorites  Tools  Help

 ←      →      ↑      %      □      □      ⟲      ✕      □      □
Back  Forward  Up    Cut   Copy  Paste  Undo  Delete Properties Views

Address  □ C:\Media Thickness

Folders              × | Name            Size | Type                          Modified
 ⊞ 3½ Floppy (A:)       | 20020617.csv     1KB   Microsoft Excel Comma Separated Values ...  6/17/02 4:57 PM
 ⊟ (C:)                 | AdjustMM.exe     94KB  Application                    11/13/02 10:42 AM
    Media Thickness     | MachinInfoMM.ini 1KB   Configuration Settings         6/17/02 4:40 PM
 ⊞ My Documents         | Opusbacc.dll     68KB  Application Extension          1/22/02 3:45 AM
 ⊞ Program Files

4 object(s)              152KB (Disk free space: 5.38GB)        My Computer
```

(5) Power off the printer and disconnect the interface cable.

3.4.2.4 Actions for NG Sensitivity Adjustment

When a CSV format file stored automatically in sensitivity adjustment is opened, the opened file contains the following. The yellow-shaded area shows errors. For error code-to-description correspondence, see the flow chart shown below.

Data stored in CSV format (Example)

Calibration of Media-thickness adjustment & Munsell correction writing   #####

	Lot:	0121 MO59970		Machin ODC-000														

IR Number	Err.Code	Check Input	Check Meas	Calb	Data-D1	Data-D2	Data-D3	Data-R1	Data-R2	Data-R3	AD-1	AD-2	AD-3	AD-Che	Munsell	Judg	Date	Time
17	0	101	107	141	101	103	102	99	105	104	754	760	762	763	FE	GOOD	#####	8:55:06
18	0	99	103	146	100	102	103	97	108	112	627	634	634	633	FE	GOOD	#####	10:14:21
37	0	96	100	145	103	101	101	101	109	107	640	653	654	654	0	GOOD	#####	10:18:42
1	0	101	105	139	98	99	103	98	98	102	772	779	781	781	3	GOOD	#####	10:38:15
13	0	101	105	136	98	103	104	91	100	104	687	697	698	697	2	GOOD	#####	10:45:58
5	0	102	98	140	101	104	101	97	106	102	752	760	759	758	2	GOOD	#####	10:58:27

Action procedure for NG sensitivity adjustment on media thickness detection part

Header: Oki Data CONFIDENTIAL

3.4.3   Inputting the density of the calibration chip for density detection

Write the calibration target adjustment value (last 2 digits in the barcode, refer to the figure below) indicated on the shutter label.

The adjustment value of the shutter must be reset when Sheet Color, density sensor, or PU sensor is replaced.

3.4.3.1 Density Adjustment Menu Setting

For the steps (1) to (8) of menu setting, see Media Thickness Detection Adjustment Calibration 3.4.2.1, steps (1) to (8).
   (9) The screen returns to the Adjust Munsell & Media screen. Press Munsell.

(10) Press Yes.

(11) The Munsell sheet correction value input screen appears.

(12) Enter the correction value marked on the barcode label on the shutter into the Input field and press OK (the Munsell sheet correction value is sent from the PC to the printer and set).

(13) When the density adjustment is completed properly, the ADJUSTMM screen and the Adjust Munsell & Media screen are brought up.

Barcode specification:
① Applied code   : code39
② Barcode digit   : 12 digits
③ Written content   :
  From the left:*1 digit
             Date4 digits   (ID barcode) method
                                 Year   1 digit - 1 digit (x) in (200x)
                                 Month   1 digit (10th, 11th, 12th month are indicated as X, Y, Z.)
                                 Day   2 digits
             Empty 4 digits   Set zeros "0000".
             2 adjustment digits (Same as the data format input manually for the printer.)
                                 00~04 for 0 to 4, FF~FC for -1 to -4.

④ Barcode length
  YC4116-1006P001 label sheet 1/4"

4.   REGULAR MAINTENANCE

4.1   Parts Replaced Regularly

It is recommended that the following parts be periodically replaced, as specified, by users (When they are not replaced, print quality is not assumed and printer problems may result).

Part Name	Time of Replacement	Condition for Replacement	Adjustment after Replacement
Large-capacity Toner Cartridge	When the message Toner Low is displayed.	15,000 pages are printed.	
Toner Cartridge		7,500 pages are printed.	
ID Cartridge	When the message Drum Life is displayed.	26,000 pages are printed. (at 3P/J)	
Fuser Unit	When the message Fuser Life is displayed.	80,000 pages are printed.	
Belt Unit	When the message Belt Life is displayed.	80,000 pages are printed. (at 3P/J)	
Feed Roller	When non-feeding of paper is frequent (a proper paper amount is loaded).	120,000 pages are printed (this is given as a guide).	

The above regular part replacement is performed by a user.

4.2   Cleaning

The inside and outside of this printer should be cleaned with waste and a hand cleaner, if necessary.

Note: Do not touch the Image drum terminals, LED lens array and LED head connector.

4.3   Cleaning of LED Lens Array

When longitudinal white bands or stripes (void or light areas) appear on a printed paper surface, the LED lens array should be cleaned.

Note: The LED head cleaner must be used to clean the LED lens array. (The LED head cleaner is included in the Toner cartridge package.)

White band, white stripes
(Void or light area)

4.4   Cleaning Pick-up Roller

When paper is not fed normally, the Pick-up roller should be cleaned.

Note: Use a soft cloth, alcohol, etc. So as not to damage the roller surface.

5. TROUBLESHOOTING PROCEDURES

5.1 Precautions before troubleshooting

(1) Confirm the basic inspection items described in the user manual.

(2) Obtain as much information regarding the problem from the user as possible.

(3) Check the printer in a condition close to that upon generating the problem.

5.2 Precautions before handling an abnormal image

(1) Confirm that the environment for using this printer is appropriate.

(2) Confirm that consumables (toner, drum cartridge) are replaced appropriately.

(3) Confirm that paper is accurate. Refer to paper specifications.

(4) Confirm that the drum cartridge is set appropriately.

5.3 Precautions upon handling an abnormal image

(1) Do not touch or allow foreign objects to contact the OPC drum surface.

(2) Do not expose the OPC drum to direct sunlight.

(3) Do not touch the fuser unit as it is heated significantly.

(4) Do not expose the image drum to light for longer than five minutes in room temperature.

5.4 Preparing for Troubleshooting

(1) Operator panel display

Problems that occur with the printer are indicated in the LCD.
Apply proper remedies according to the message indicated in the LCD.

5.5 Troubleshooting Procedure

Confirm the problem in the following method when the printer generates a problem.

```
┌──────────────────┐
│ Problem generated │
└──────────────────┘
        │
        ├──▶ ┌──────────────────┐     ┌──────────────────┐     ┌──────────────────┐
        │    │ Problem is displayed │─▶│ Repair using the "LCD │─▶│ Repair in detail using │
        │    │ in LCD.              │  │ message list" (see 5.5.1). │  │ troubleshooting flow   │
        │    │                      │  │                      │  │ (see 5.5.2).          │
        │    └──────────────────┘     └──────────────────┘     └──────────────────┘
        │
        └──▶ ┌──────────────────┐                               ┌──────────────────┐
             │ Abnormal image       │──────────────────────────▶│ Repair in detail using │
             │ (or problems that are │                          │ troubleshooting flow   │
             │ not displayed in the  │                          │ (see 5.5.3).          │
             │ LCD)                  │                          │                      │
             └──────────────────┘                               └──────────────────┘
```

5.5.1   LCD message list

When the printer detects a non-recoverable error, the following service call error is displayed in the LCD.

Service call
nnn: error

Note: nnn is an error code.

When [Service call] is displayed, error information that corresponds to the error code appears in the bottom line in the LCD. Error codes, their definitions and remedies are described in Table 5-1-1.

Table 5-1-1 Operator Alarms (1/6)

Message	Cause	Error Description		Solutions
Service Call 001: Error ~ 011: Error	CPU Exception	Does error display reappear? Does error display reappear?	Yes Yes	Turn power OFF and ON. Replace TIG board. (Replace EEPROM)
Service Call 020: Error	CU ROM Hash Check Error 1	Is program ROM DIMM set properly? Is error recovered by replacing program ROM DIMM?	No Yes No	Reset program ROM DIMM. Replace program ROM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 030: Error	CU Slot1 DIMM RAM Check Error	Is subject RAM DIMM set properly? Is error recovered by replacing subject ROM DIMM?	No Yes No	Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 031: Error	CU Slot2 DIMM RAM Check Error	Is subject RAM DIMM set properly? Is error recovered by replacing subject ROM DIMM?	No Yes No	Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 032: Error	CU Slot3 DIMM RAM Check Error	Is subject RAM DIMM set properly? Is error recovered by replacing subject ROM DIMM?	No Yes No	Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 035: Error	Slot1 RAM Spec Error. The CU RAM Slot1 DIMM specification is not supported.	Is RAM DIMM genuine? Is subject RAM DIMM gap setting proper? Is error recovered by replacing subject ROM DIMM?	No No Yes No	Use genuine RAM DIMM. Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 036: Error	Slot2 RAM Spec Error. The CU RAM Slot2 DIMM specification is not supported.	Is RAM DIMM genuine? Is subject RAM DIMM gap setting proper? Is error recovered by replacing subject ROM DIMM?	No No Yes No	Use genuine RAM DIMM. Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 037: Error	Slot3 RAM Spec Error. The CU RAM Slot3 DIMM specification is notsupported.	Is RAM DIMM genuine? Is subject RAM DIMM gap setting proper? Is error recovered by replacing subject ROM DIMM?	No No Yes No	Use genuine RAM DIMM. Reset subject RAM DIMM. Replace RAM DIMM. Replace TIG board. (Replace EEPROM)
Service Call 040: Error	CU EEPROM Error	Is error recovered by replacing EEPROM on CU board?	Yes No	Replace EEPROM. (Recover user environment.) Replace TIG board. (Replace EEPROM)
Service Call 041: Error	CU Flash Error Flash ROM error on CU board.	Does error display reappear?	Yes	Replace TIG board. (Replace EEPROM.)

Table 5-1-1 Operator Alarms (2/6)

Message	Cause	Error Description		Solutions
Service Call 042: Error ~ 044: Error	Flash File SYSTEM Error	Failed access to Flash set directly on CU board.		Press ⓪, ③, ⑤, ⑥ to turn power ON, release buttons when [FLASH FORMAT] appears, wait until [ON-LINE] (2sec) and replace TIG board if symptom does not change.
Service Call 048: Error	CU ROM for PS+PCL was set in Non-PS device.	Is proper program ROM set?	Yes No	Replace program ROM DIMM. Replace with proper program ROM DIMM.
Service Call 049: Error	CU type mismatch CU ROM does not match with the device.	Is proper program ROM set?	Yes No	Replace program ROM DIMM. Replace with proper program ROM DIMM.
Service Call 050: Error	Operater Panel Error	Does error display reappear?	Yes	Refer to no LCD display flow chart.
Service Call 051: Error	CU Fan Error Abnormal CPU cooling fan on CU board.	Is connector set properly on CU board? Is error recovered by replacing fan?	No Yes No	Connect properly. Replace fan. Replace TIG board. (Replace EEPROM.)
Service Call 063: Error	Network comm. Error Abnormal H/W I/F between CU-NIC.	Is network board set properly? Is error recovered by replacing network board?	No Yes No	Set properly. Replace Network. Replace TIG board. (Replace EEPROM.)
Service Call 065: Error	NIC Combination Error	Is proper Network board for the model set?	Yes No	Replace NIC card. Replace with proper Network board (MLETB11, etc.).
Service Call 070: Error	CANT_HAPPEN PS firmware fault detected.	Confirm that error is recovered by turning power OFF/ON.	No	Replace TIG board. (Replace EEPROM.)
Service Call 072: Error	Engine communication error I/F error between PU-CU.	Is CU assembly set properly? Is error recovered by replacing TIG board?	No Yes No	Set properly. Replace TIG board. (Replace EEPROM.) Replace PU board.
Service Call 073: Error ~ 075: Error	Video overrun detect	Is CU assembly set properly? Is error recovered by replacing TIG board?	No Yes	Set properly. Replace TIG board. (Replace EEPROM.)
Service Call 090: Error	Finisher Stapler Motor Error	Is the error message displayed again?	Yes	See Finisher Maintenance Manual.
Service Call 091: Error	Finisher Tray Elevator Error	Is the error message displayed again?	Yes	See Finisher Maintenance Manual.
Service Call 092: Error	Finisher Bin2 Exit Belt Motor Error	Is the error message displayed again?	Yes	See Finisher Maintenance Manual.
Service Call 093: Error	Finisher Jogging Motor Error	Is the error message displayed again?	Yes	See Finisher Maintenance Manual.
Service Call 094: Error	Finisher Main Feed Motor Error	Is the error message displayed again?	Yes	See Finisher Maintenance Manual.
Service Call 102: Error	Error in engine RAM read/write detected at power ON.	Does error reoccur?	Yes	Replace engine control board (K7N).
Service Call 103: Error	Error in engine SRAM read/write detected at power ON.	Does error reoccur?	Yes	Replace engine control board (K7N).
Service Call 104: Error	Error in engine EEPROM check total detected at power ON.	Does error reoccur?	Yes	Replace engine control board (K7N).

Table 5-1-1 Operator Alarms (3/6)

Message	Cause	Error Description		Solutions
Service Call 105: Error	EEPROM not detected at power ON.	Does EEPROM exist? Does error reoccur?	Yes Yes	Check for EEPROM and set if not found. Replace engine control board (K7N).
Service Call 106: Error	Error in engine control logic detected at power ON.	Does error reoccur?	Yes	Replace engine control board (K7N).
Service Call 107: Error	Engine ROM check sum error.	Does error reoccur? Is error recovered by reloading PU F/W?	Yes No	Reload PU I/F. Replace engine control board (K7N).
Service Call 110: Error ~ 116: Error	Option unit for different model detected. 110: EnvelopeFeeder 111: Duplex unit 112: 2nd Tray 113: 3rd Tray 114: 4th Tray 115: 5th Tray 116: Finisher	Is a proper option unit for the printer set?	Yes No	Set proper option unit. Check connections and turn power ON. If error is not recovered, replace the unit.
Service Call 120: Error	PU unit fan motor error.	1) Is fan in PU unit operating? 2) Error reoccurs after replacing fan motor.	No Yes Yes	Replace fan motor. Replace engine control board (K7N). Replace engine control board (K7N).
Service Call 121: Error	High-voltage power supply I/F error.	Is cable between PU board andhigh-voltage power LSI connected properly?	No Yes	Connect properly. Replace high-voltage power supply. Check improper connections for high-voltage.
Service Call 122: Error	Low-voltage power supply fan error. Low-voltage power supply temperature error.	1) Is fan in low-voltage power supply unit operating? 2) Error reoccurs after replacing fan motor.	No Yes Yes	Replace fan motor. Replace low-voltage power supply. Replace low-voltage power supply.
Service Call 123: Error	Improper environment humidity detected by sensor.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace humidity sensor.
Service Call 124: Error	Improper environment temperature detected by sensor.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace humidity sensor.
Service Call 125: Error	Error detected at MT home position.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace MT.
Turn power OFF and wait 126: Dew error	Sensor dew error.	Sensor dew error detected.		Turn ON power after a while.
Service Call 127: Error	Error detected at the fuser unit cooling fan.	1) Does the fuser unit cooling fan operate? 2) Does the error repeat after fuser unit cooling fan replacement?	No Yes Yes	Replace the fuser unit cooling fan. Replace the engine control PWB (K7N). Replace the engine control PWB (K7N).
Service Call 130: Error	Temperature rise detected at LED head.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes Yes	Leave alone for 30 min. Turn power OFF. Leave for 30 min., then turn power ON. Replace LED head.
Service Call 131: Y Head 132: M Head 133: C Head 134: K Head	Same unit not detected upon power ON or opening cover.	1) Is error message displayed? 2) Is LED head properly set? 3) Does error reoccur?	Yes No Yes	Confirm that LED head is set properly. Turn power ON again. Replace LED head assembly.
Service Call 140: Y ID 141: M ID 142: C ID 143: K ID	Error detected at proper ID position.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn power ON again. Replace drum contacct assembly.

Table 5-1-1 Operator Alarms (4/6)

Message	Cause	Error Description		Solutions
Service Call 150: Y 151: M 152: C 153: K	When a fuse could not be disconnected in the ID unit.	Is ID unit set properly?	Yes	Check cable connections and replace engine board.
Service Call 154: Error	When belt unit fuse cannot be disconnected.	Is belt unit set properly?	Yes	Check cable connections and replace engine board.
Service Call 155: Error	When fuser unit fuse cannot be disconnected.	Is fuser unit set properly?	Yes	Check cable connections and replace engine board.
Service Call 160: Y Toner 161: M Toner 162: C Toner 163: K Toner	Error detected by toner sensor.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Replace toner sensor or assembly (Y71-PWB). Same as above.
Service Call 170: Error 171: Error 174: Error 175: Error	Short circuit in fuser thermistor or open detected (high temp. or low temp.)	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace thermistor and turn power OFF. Leave aside for 30 min.
Service Call 172: Error 176: Error	Thermistor indicates high-temperature error.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace thermistor and turn power OFF. Leave aside for 30 min.
Service Call 173: Error 177: Error	Thermistor indicates low-temperature error.	1) Is error message displayed? 2) Does error reoccur?	Yes Yes	Turn ON power again. Replace thermistor and turn power OFF. Leave aside for 30 min.
Service Call 179: Error	Wrong fuser standard.	1) Does fuser match with model and power voltage? 2) Error reoccurs after setting fuser properly.	No Yes Yes	Set proper fuser. Check if fuser is set properly. Replace fuser.
Service Call 180: Error ~ 186: Error	Communication disability with option unit detected by engine. 180: Envelope Feeder (Not used) 181: Duplex unit 182: Tray2 unit 183: Tray3 unit 184: Tray4 unit 185: Tray5 unit 186: Finisher unit	Is the error message displayed sgin?	Yes	Check the connector between the printer and the unit, and reinstall the unit.
Service Call 187: Error	Communication with control panel disabled	Is cable properly connected to control panel?	No Yes	Connect properly. Replace control panel and cable.
Service Call 200: Error ~ 202: Error	Error occurered while writing over the PU firmware. (This does not occur at user level.)	Turn the printer OFF/ON, and retry to download the PU firmware, again.	-	Usually, the procedure (PU firmware download) which isn't done.
POWER OFF/ON 209: DOWNLOAD ERROR	Downloading Media Table to PU has failure. (Related to Custum Media Type)	Turn the printer OFF/ON, and retry to download the PU firmware, again.	-	Usually, the procedure (PU firmware download) which isn't done.
Service Call 203: Error ~ 208: Error 210: Error ~ 214: Error 0xFFE: Error 0xFFF: Error	An error was detected of the CU program.	Reinstall the CU board. Is the error message displayed again?	Yes	Please report the address (24 charactoers) in the indicated LCD (if possible). Turn the printer OFF/ON.

Table 5-1-1 Operator Alarms (5/6)

Message	Cause	Error Description		Solutions
Close cover 310: Top cover open	Printer engine cover open.	1) Check if top cover is open. 2) Check if cover switch is proper.	Yes Yes No	Close top cover. Close side cover. Replace cover switch.
Reset fuser 320: Fuser error	Same unit not detected upon power ON or opening cover.	1) Is error message displayed? 2) Is fuser unit set properly? 3) Does error reoccur?	Yes No Yes	Check if fuser is set properly. Reset fuser and turn ON power again. Replace fuser unit assembly.
Turn power OFF and wait 321: MOTOR OVERHEAT	Printer cannot be used temporarily due to motor overheat.			Turn ON power after a while.
Open/close cover 323: Paper thickness error	Sensor output out of range with no media. (Only for Factory Mode)	1) Are foreign objects mixed in sensor? 2) Does printer recover when detecting paper thickness by opening/closing tray? 3) Does printer recover by power OFF/ON.	Yes No	Remove foreign objects. Normal.
Open/close cover 324: Paper thickness error	Sensor output gap out of range with no media. (Only for Factory Mode)	1) Are foreign objects mixed in sensor? 2) Does printer recover when detecting paper thickness by opening/closing tray? 3) Does printer recover by power OFF/ON.	Yes No	Remove foreign objects. Normal.
Open/close cover 325: Paper thickness error	Media detect value out of range.	1) Is different media type mixed in? 2) Is media being double fed?	Yes	Remove foreign objects.
Open/close cover 326: Paper thickness error	U-Heavy mode media detect value out of range.	Is different media type mixed in?	Yes	Remove foreign objects.
Reset belt 330: Belt error	Same unit not detected upon power ON or closing cover.	1) Is error message displayed? 2) Is belt unit set properly? 3) Does error reoccur?	Yes No Yes	Check set condition of belt unit. Reset belt unit and turn power ON again. Replace belt unit assembly.
Reset drum 340~343: Drum error	Same as above.	1) Is error message displayed? 2) Is image drum set properly? 3) Does error reoccur?	Yes No Yes	Check set condition of ID. Turn power ON again. Replace ID unit assembly.
Set new drum 350: Yellow drum life 351: Magenta drum life 352: Cyan drum life 353: Black drum life	ID unit life.	Right after replacing ID unit?	Yes No	Check ID unit life. Replace ID unit.
Set new fuser 354: Fuser life	Fuser life (occurs when fuser life continuation is OFF).	Right after replacing fuser?	Yes No	Check fuser life. Replace fuser.
Set new belt 355: Belt life	Belt life notified (alarm). Print N-count by opening and closing cover.	Right after replacing belt?	Yes No	Check belt life. Replace belt.
Set new belt 356: Belt life	Waste toner belt life notified (alarm). Print N-count by opening and closing cover. N=20	Right after replacing belt?	Yes No	Check belt life. Replace belt.
Set duplex unit 360: Duplex unit is open.	When duplex unit is removed from printer.	Does error recover by resetting duplex unit?	Yes No	Normal. Replace duplex unit or engine board.

Table 5-1-1 Operator Alarms (6/6)

Message	Cause	Error Description		Solutions
Check DUPLEX 370: Paper jam	Paper jam detected after paper rotated in duplex unit.	Check paper jam in duplex unit.	Yes No	Remove jammed paper. Check/replace duplex unit.
Check DUPLEX 371: Paper jam	Paper jam during paper feed from duplex unit.	Check paper jam in duplex unit.	Yes No	Remove jammed paper. Check/replace duplex unit.
Check DUPLEX 372: Paper jam		Check miss-feed in duplex unit.	Yes No	Remove miss-fed paper and close cover. Check/replace duplex unit.
Open front cover 380: Paper jam	Paper jam during paper feed from cassette 1, 2, 3, 4 or 5.	Check miss-feed in duplex unit.	Yes No	Remove miss-fed paper and set cassette. Check/replace cassette 1, 2, 3, 4, or 5.
Open top cover 381: Paper jam	Paper jam detected between black ID and fuser	1) Check paper jam between yellow ID and fuser. 2) Check fuser unit load.	Yes No	Remove jammed paper. Replace fuser unit.
Open top cover 382: Paper jam	Paper jam detected in fuser or during paper ejection from fuser.	1) Check paper jam in fuser and between yellow ID and fuser. 2) Check if paper ejection switch is proper.	Yes No	Remove jammed paper. Replace paper ejection switch.
Open top cover 383: Paper jam	Paper jam detected when paper started to enter duplex print unit.	Check paper jam in duplex unit or at entrance.	Yes No	Remove jammed paper. Check/replace duplex unit.
Open top cover 389: Paper jam	Jam generated in paper path.	Open front cover and check jammed paper.	Yes	Remove jammed paper.
Check MP tray 390: Paper jam	Paper jam during paper feed from MT.	Check for miss-fed paper around MT cassette.	Yes No	Remove miss-fed paper and close cover. Check/replace MT.
Check tray * 391~395: Paper jam	Paper jam detected between cassette and black ID.	1) Check jammed paper between cassette and yellow ID. 2) Check if paper entry switch is normal.	Yes No	Remove jammed paper. Replace entry switch.
Open top cover 400: Paper size error	Non-set paper (45mm or above) detected by printer engine.	1) Is paper custom size? 2) Is paper standard size?	Yes Yes No	No treatment required. Adjust paper size guide in cassette. Replace paper size board (PXC PWB).
Refill toner 410: Yellow 411: Magenta 412: Cyan 413: Black	Certain toner is almost empty.	1) Selected toner cartridge is almost empty. 2) Check if selected toner cartridge is normal.	Yes No	Replace with new toner kit. Replace selected toner sensor.
Remove paper 480: Stacker full	Paper ejection stacker is full.	1) Check if stacker is full. 2) Check if stacker full sensor is operating properly.	Yes No	Remove paper from stacker. Replace stacker full sensor.
Set *** 490: No paper in MP tray (* stands for A4 B4, etc.)	No paper in selected cassette. cassette is not set, or paper ran out in cassette being used.	1) Check if paper is empty in MT. 2) Check if paper-end sensor is operating properly.	Yes No	Set paper in MT. Replace paper-end sensor.
Set *** 491~495: No paper in * tray (* stands for A4 B4, etc.)	Paper empty in cassette 1, 2, 3, 4, or 5.	1) Check if paper is empty in selected cassette. 2) Check if paper-end sensor is operating properly.	Yes No	Set paper in selected cassette. Replace the corresponding paper-end sensor.
Replace fuser	Fuser counter exceeded life.	1) Is error message displayed? 2) Was fuser unit just replaced?	Yes No	Check fuser unit life. Replace fuser immediately or at next maintenance.
Paper in * tray nearly empty	Paper near end detected.	Are only few papers remaining in tray? (approx. 30 sheets or less)	Yes No	Refill paper. Check paper near end sensor.
Disk operation error	Cannot write in HDD.	Is faulty operation being applied?	No Yes	Check manual operation. HDD abnormality. Replace HDD.

5.5.2   Preparing for troubleshooting

(1)   Operator panel display
Problems that are generated in this device are indicated in the LCD.
Apply proper measures according to the message displayed in the LCD.

No.	Problem	Flow Chart No.
1	The printer does not function properly after power ON.	①

2	Jam error
	  Feed jam (1st tray)
	  Feed jam (multipurpose tray)
	  Path jam
	  Exit jam
	  Duplex jam
		②-1
		②-2
		②-3
		②-4
		②-5

3	Paper size error	③
4	I/D up/down error	④
5	Fuser unit error	⑤
6	Fan motor error	⑥

Note: When changing the engine board (K7N PWB), remove the EEPROM chip from the old
board and install it on the newly replaced board

(2)   CU assembly troubleshooting

No operation

Is an error message displayed?

YES   Perform according to the error message.

No   Is black displayed in the top and bottom lines of the operator panel LCD?

No   Check the power voltage   3.3V, 5V
3.3V is open space   2 pin for JTAGW
5V is 2, 3 pins for open space HD5V.

No   Replace the power supply.

YES   Check the PU board and operator panel board.

YES   Is ROM DIMM A set properly?

No   Set a program DIMM to ROM DIMM A properly.
If the error is not recovered, replace the CU board.

YES   Replace the CU board.
Remove EEPROM from the old board and install it on the new board.

① The printer does not function properly after power ON.

- Turn the power OFF then ON.
- Is ▬▬▬▬▬▬▬▬▬▬▬▬ displayed? (Approx. 1 sec.)
  ▬▬▬▬▬▬▬▬▬▬▬▬

    No   Is the AC cable connected properly?

       No Connect the AC cable properly.

    Yes Is +5V output to the panel connector (OPTN connector) on the engine board (K7N PWB)?
          Pin 10, 11, 18: +5V   Pin 5, 7, 15,20: 0V

       Yes Is +5V output to the panel connector on the relay board (Y73 PWB)?
            Pin 5: +5V   Pin 2: 0V

          No   Replace the relay board.

       Yes Is the operator panel cable connected properly?

          No   Connect the cable properly.

       Yes Replace the operator panel cable. Is operation recovered?

          No   Replace the cover assembly of the operator panel.

          Yes End.

    No   Is +5V output to the power connector on the engine board (K7N PWB)?
          Pin 5, 6, 7, 8: +5V   Pin 1, 2, 3, 4, 9, 10, 11: 0V

       No   Check the power connection connector, then replace the low-voltage power supply unit.

       Yes Replace the engine board.

  Yes   Are the following voltages output to the PU IF connector on the main board?
          Pin 137-147, 187-197   : +5V   Pin 125-136, 175-186   : +3.3V
          Pin 148, 198   : +12V   Pin 101-124, 149-174, 199, 200 : 0V

    Yes Replace the main board.

  No   Is the following voltage output to the power connector on the engine board?
          Pin 5, 6, 7, 8   : +5V
          Pin 15   : +12V
          Pin 12, 13, 14   : +34V   Pin 1, 2, 3, 4, 9, 10, 11   : 0V

    Yes Replace the engine board.

  No   Replace the low-voltage power supply unit.

②-1 Feed jam (1st tray)

- Do feed jams occur right after power ON?

    - Yes   Is the jam at the entrance cassette sensor or entrance MT sensor?

        Yes   Remove the jammed paper.

    (A)

    - No   Does the sensor lever (entrance cassette sensor or entrance MT sensor) function properly?

        No   Replace the faulty sensor lever.

    - Yes   Does the sensor (input cassette sensor, entrance MT sensor) function properly?
      Operate each sensor lever and check the signal on the FSENS connector pin on the engine board (K7N PWB).
      Pin 4: Entrance sensor / Pin 2: Entrance MT sensor

        No   Check the connection of the NO signal cable, then replace the engine.

    Yes   Check the signal cable connection, then replace the sensor board (R71 PWB).

- No   Do feed jams occur right after papers are absorbed?

    - Yes   Did the paper reach the entrance cassette sensor or entrance MT sensor?

        Yes   Proceed to (A).

    - No   Replace the feed roller or paper separation frame assembly of the paper cassette.

- No   Is the main feed motor rotating?

    Yes   Replace the feed roller or paper separation frame assembly of the paper cassette.

- No   Is the main feed motor resistance within the regulated value (approx. 4Ω)?

    No   Replace the main feed motor.

- Yes   Is 34V output to fuse F2 and F4 on the engine board?

    No   Replace the low-voltage power unit.

- Yes   Check the gear mesh status and cable connections, then replace the engine board.

②-2 Feed jam (multipurpose tray)

- Do feed jams occur right after power ON?

    - Yes Is the jam at the entrance cassette sensor or entrance MT sensor?

        Yes Remove the jammed paper.

      (A)

    - No Does the sensor lever (entrance MT sensor) function properly?

        No Replace the faulty sensor lever.

    - Yes Does the sensor (entrance MT sensor) function properly?
      (Operate each sensor lever and confirm that the sensors function properly in the switch scan test in the system maintenance mode. Also check the FSENS connector pin signal on the engine board (K7N PWB).)
      PIN 2: Entrance MT sensor

        No Check the signal cable connection, then replace the sensor board (R71 PWB).

    - Yes Check the signal cable connection, then replace the engine board.

  - No Do feed jams occur right after papers are absorbed?

    - Yes Did the paper reach the entrance MT sensor?

        Yes Proceed to (A).

    - No Replace the multipurpose tray assembly.

  - No Is the resist motor rotating?

    - No Is 34V output to fuse F4 on the engine board?

        No Replace the low-voltage power unit.

    - Yes Check the cable connections, then replace the engine board.

  - Yes Check the cable connections, then replace the engine board.

②-3 Path jam

- Do path jams occur right after power ON?

    - Yes Is the jam at the entrance belt sensor?

        Yes Remove the jammed paper.

    (A)

    - No Does the light sensor lever function properly?

        No Replace the light sensor lever.

    - Yes Does the belt sensor lever function properly?
      (Operate the sensor lever and check the FSENS connector pin signal on the engine board (K7N PWB).)
      Pin 6: Entrance belt sensor

        No Check the cable connections, then replace the sensor board (R71 PWB).

    - Yes Check the signal cable.
      Is it connected properly?

        No Connect the cable properly.

    - Yes Replace the engine board.

- No Do path jams occur right after papers are absorbed?

    - Yes Did the paper reach the light sensor?

        Yes Proceed to (A).

    - No Is the resist motor rotating?

        - No Is the main feed motor resistance within the regulated value (approx. 7.9Ω)?

            No Replace the resist motor.

        - Yes Check the gear mesh status, then replace the engine board.

    - Yes Replace resist motor A or B.

- No Do path jams occur upon loading paper?

    - Yes Is the belt motor rotating?

        - No Is the belt motor resistance within the regulated value (approx. 7.9Ω)?

            No Replace the belt motor.

        - Yes Check the gear mesh status, then replace the engine board.

    - Yes Check the gear mesh status, then replace the belt cassette assembly.

- No End.

②-4 Exit jam

- Do exit jams occur right after power ON?

    - Yes   Is the jam at the paper exit sensor?

        - Yes   Remove the jammed paper.

    - No   Does the paper exit sensor lever function properly?

        - No   Replace the paper exit sensor lever.

    - Yes   Does the paper exit sensor function properly?
        (Operate each sensor lever and confirm that the sensors function properly in the switch scan test in the system maintenance mode. Also check the signal of connecter PARTTEMP Pin 8 on the engine board (K7N PWB).)

        No   Check the signal cable connections, then replace the paper exit sensor.

    - Yes   Replace the engine board.

- No   Is the cover of the face-up stacker fully opened or closed?

    No   Open or close the cover completely.

- Yes   Is the heat motor rotating?

    - No   Is the heat motor resistance within the regulated value (approx. 7.9Ω)?

        No   Replace the heat motor.

    - Yes   Is 34V output to power connector 12-14 pins on the engine board?

        No   Replace the low-voltage power unit.

    - Yes   Check the cable connections, then replace the engine board.

- Yes   Is the paper ejection guide functioning properly?

    No   Replace the paper ejection guide.

- Yes Replace the engine board.

②-5 Duplex jam

• Do path jams occur right after power ON?

    • Yes Is there paper in the duplex print unit?

        Yes Remove the jammed paper.

     (A)

    No Do the duplex unit entrance sensor, rear sensor, and sensor lever of the front sensor function properly?

        No   Replace the faulty sensor lever.

    Yes Do the duplex unit entrance sensor, rear sensor, and front sensor function properly?
        (Check if the level of each sensor is "no paper" with the switch scan test in the system maintenance mode.)

        No   Check the cable connections, then replace the faulty sensor.

    Yes Check the signal cable connection.
        Is it connected properly?

        No   Connect the cable properly.

    Yes Replace the duplex print control board (V73 PWB)

No   Do path jams occur right after papers are absorbed?

    Yes Did the paper reach the duplex print rear sensor?

        • Yes Proceed to (A).

    No Is the duplex print motor rotating?

        No   Is the duplex print motor resistance within the regulated value (approx. 6.7Ω)?

           No   Replace the duplex print motor.

        Yes Check the gear mesh status, then replace the duplex print board (V73 PWB).

    Yes Replace resist motor A or B.

No   Replace the duplex print unit.

③ Paper size error

• Is paper of regulated size being used?

    No   Use paper of regulated size.

    Yes   Is a jam detected by the entrance FF sensor or paper width sensor?

        Yes Remove the jammed paper.

    No   Is the entrance FF sensor lever functioning properly?

        No   Place the faulty sensor lever.

    Yes   Is the entrance FF sensor functioning properly?
            (Check the FSENS connector pin signal on the engine board (K7N PWB).)
            Pin 4: Entrance FF sensor

        No   Check the cable connections, then replace the sensor board (R71 PWB).

    Yes   Is the entrance belt sensor functioning properly?

        No   Place the faulty sensor lever.

    Yes   Is the entrance belt sensor functioning properly?
            (Operate the sensor lever and confirm that the sensor functions properly in the switch scan test in the system maintenance mode. Also check the FSENS connector pin signal on the engine board (K7N PWB).)
            Pin 6: Entrance belt sensor

        No   Check the cable connections, then replace the sensor board (R71 PWB).

    Yes   Are all paper size detection switch on the size detection board (PXC-PWB) functioning properly?
            (Press the paper size detection switch and check the PSIZE connector pin signal on the engine board.)
            Pin 3: Paper size detector 1
            Pin 4: Paper size detector 2
            Pin 5: Paper size detector 3
            Pin 6: Paper size detector 4

        No   Check the cable connections, then replace the paper size detection board (PXC-PWB).

    Yes   Check the cable connections, then replace the engine board.

④ Up/Down movement error of the image drum unit (ID)

• Turn the printer OFF, then turn it ON after a few seconds.

• Are all ID drums rotating properly during print operation?

No Is the ID motor resistance within the regulated value (approx. 2.4Ω)?

No Replace the faulty IDU motor.

Yes Is 34V output to F3 and F5 on the engine board?

No Replace the low-voltage power unit.

Yes Check the cable connections, then replace the engine board.

Yes Is the IDU sensor terminal functioning properly?

No Check the gear mesh status and sensor terminal function, the replace the gear or sensor terminal.

Yes Is the ID sensor terminal functioning properly?
(Check the JODEN connector pin signal on the driver board (K7N PXB).)
Pin 12   : IDU sensor - yellow
Pin 2   : IDU sensor - magenta
Pin 4   : IDU sensor - cyan
Pin 14   : IDU sensor - black
Are all at 5V level or 0V level?

No Replace the connection board (N71 PWB).

Yes Check the cable connection between the connection board (N71 PWB) and engine board (K7N PWB), then replace the engine board.

⑤ Fuser unit error

• Do fuser errors occur right after power ON?

   (A)

   • Yes Is the heat roller thermister disconnected or generating a short circuit? (See Fig. 5-1) (Approx. 190k-980kΩ in room temperature of 0-43 degrees Celsius.)

      • Yes   Replace the fuser unit.

   No Is the back-up roller thermister disconnected or generating a short circuit? (See Fig. 5-1) (Approx. 190k-980kΩ in room temperature of 0-43 degrees Celsius.)

      • Yes Replace the fuser unit.

   No

No Does a fuser unit error occur approx. three minutes after power ON?

• No Proceed to (A).

Is the heater in the fuser unit turned ON? (Is it hot?)

• Yes Replace the engine board.

No Replace the fuser unit.

No Is AC voltage output between CN1 connector pin 1 and pin 3 in the low-voltage power unit?

• No Replace the low-voltage power unit.

Yes Replace the fuser unit.

Back-up roller thermister

Heat roller thermister

Figure 5.1

⑤ Motor fan error

- Does the low-voltage power fan rotate at power ON?

    - No Is 34V output to fuse F7 on the engine board (K7N PWB)?

        - No Is 34V output to the power connector on the engine board (K7N PWB)?
          34V: Pin 12, 13, 14

        - No Check the cable connections, then replace the low-voltage power unit.

        - Yes Replace the engine board.

    - Yes Was the low-voltage power board replaced?

        - Yes End.

    - No Replace the low-voltage power board.

- Yes Does the engine board fan rotate at power ON?

    - No Is 34V output to fuse F7 on the engine board (K7N PWB)?

        - No Is 34V output to the power connector on the engine board (K7N PWB)?
          34V: Pin 12, 13, 14

        - No Check the cable connections, then replace the low-voltage power unit.

        - Yes Replace the engine board.

    - Yes Replace the engine board fan.

- Yes End.

5.5.3   Troubleshooting for abnormal images

Apply remedies according to the following table when printed images are abnormal as shown below.

Abnormal Image	Flowchart No.
The entire image is faint or the color is irregular. (Figure 5.2-Ⓐ)	①
The white portion is dirty. (Figure 5.2-Ⓑ)	②
A white page is output. (Figure 5.2-Ⓒ)	③
Streaks or solid lines appear in the vertical direction. (Black line, color line / black streak, color streak) (Figure 5.2-Ⓓ)	④
White solid lines / streaks or blurred color lines / streaks appear in the vertical direction. (Figure 5.2-Ⓕ)	⑤
Faulty fusing (image blurs or scatters when touched)	⑥
Consistent abnormality (Figure 5.2-Ⓔ)	⑦
Color detachment	⑧
Color irregularity	⑨
Different color compared with the original.	⑩

Ⓐ Faint or blurred   Ⓑ Dirty white portion   Ⓒ All white

Ⓓ Vertical lines/streaks   Ⓔ Consistent abnormality   Ⓕ Vertical white lines/streaks

Figure 5.2

① An image is generally faint or the color is irregular. (Fig 5-2 Ⓐ)

• Is the amount of toner low? (Is [Toner Low] indicated?)

    Yes   Refill toner.

No   Is regulated paper used?

    No   Use regulated paper.

Yes   Is the LED head lens dirty?

    Yes Clean the LED head lens.

No   Are all items of the LED head assembly connected properly to the connection board (Y73 PWB) and engine board (K7N PWB)?

    No   Check the cable connection (between each LED head and engine board), then connect the cables between the LED head and engine board properly.

Yes   Is +5V output to the following power connector pins on the connection board (Y73 PWB)? +5V: Pin 1, 2, 3, 4, 5, 6

    Yes Is +5V output to the each LED head assemblies on the connection board (Y73 PWB)?
            3 pin for YPOW connector : LED head assembly - yellow
            3 pin for MPOW connector : LED head assembly - magenta
            3 pin for CPOW connector : LED head assembly - cyan
            3 pin for KPOW connector : LED head assembly - black

        No   Replace the connection board (Y73 PWB).

  Yes Check the cable connections, then replace the LED head assembly.

No   Check the cable connections, then replace the low-voltage power unit. Did the printer recover?

    Yes End.

No   Is 34V output to the power connector on the engine board (K7N PWB)?
            +34V: Pin 12, 13, 14

    No   Check the cable connections, then replace the low-voltage power unit.

Yes   Is 34V output to the HVOLT connector pin 2 on the engine board (K7N PWB)?

    No   Replace the engine board.

Yes   Check the cable connections, then replace the high-voltage power unit or belt cassette assembly.

    Yes End.

No   Is the I/D unit terminal connected properly to the contact assembly. (See Fig. 5-2)

    No   Connect the I/D unit terminal properly to the contact assembly.

Yes   Replace the image drum.

    Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
            2. If EEPROM is not replaced, refer to section 3.2.2.

② Dirty Background. (Fig. 5-2 Ⓑ)

- Was the image drum exposed to external light for a long time?

  Yes Replace the I/D unit.

 No Is the roller in the fuser unit dirty?

  Yes Replace the fuser unit.

 No Correct the PAPER THICKNESS setting.
 Light: 64 g/m2 Medium Light: 64 to 74 g/m2 Medium: 75 to 90 g/m2
 Medium Heavy: 91 to 104 g/m2 Heavy: 105 to 120 g/m2 Ultra Heavy 121 to 203 g/m2
 Transparency

  No Set [Paper Thickness] properly.

 No Is the LED head assembly connected properly to the connection board (Y73 PWB)?

  No Connect the LED head assembly properly to the connection board (Y73 PWB).

 Yes Is +5V output to the following power pins on the connection board (Y73 PWB)?
 +5V: Pin 1, 2, 3, 4, 5, 6

  - Yes Is +5V output to the following cable connector pins between the connection board (Y73 PWB) and LED head assembly?
   3 pin for YPOW connector : LED head assembly - yellow
   3 pin for MPOW connector : LED head assembly - magenta
   3 pin for CPOW connector : LED head assembly - cyan
   3 pin for KPOW connector : LED head assembly - black

   No Replace the connection board (Y73 PWB).

  Yes Check the cable connections, then replace the LED head assembly.

 No Check the cable connections, then replace the low-voltage power unit. Did the printer recover?

  Yes End.

 No Is 34V output to the power connector on the engine board (K7N PWB)?
 +34V: Pin 12, 13, 14

  No Check the cable connections, then replace the low-voltage power unit.

 Yes Is 34V output to the power connector pin 2 on the engine board (K7N PWB)?
 +34V: Pin 12, 13, 14

  No Replace the engine board.

 Yes Check the cable connections, then replace the high-voltage power unit or belt cassette assembly.

  Yes End.

 No Is the I/D unit terminal connected properly to the contact assembly. (See Fig. 5-2)

  No Connect the I/D unit terminal properly to the contact assembly.

 Yes Replace the image drum unit.

  Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
    2. If EEPROM is not replaced, refer to section 3.2.2.

③ White page (Fig 5-2 Ⓒ)

- Is the LED head assembly connected properly to the connection board (Y73 PWB) or engine board (K7N PWB)?

  NO Connect the cables, connect the LED assembly to the connection board (Y73 PWB), and engine board properly.

YES Is +5V output to the following power connector pins on the connection board (Y73 PWB)?
+5V: Pin 1, 2, 3, 4, 5, 6

  - YES Is +5V output to the following cable connector pins between the connection board (Y73 PWB) and LED head assembly?
3 pin for YPOW connector : LED head assembly - yellow
3 pin for MPOW connector : LED head assembly - magenta
3 pin for CPOW connector : LED head assembly - cyan
3 pin for KPOW connector : LED head assembly - black

    NO Replace the connection board (Y73 PWB).

  YES Check the cable connections, then replace the LED head assembly.

NO Is 34V output to the power connector on the engine board (K7N PWB)?
+34V: Pin 12, 13, 14

  NO Check the cable connections, then replace the low-voltage power unit.

YES Is 34V output to HVOLT connector pin 2 on the engine board (K7N PWB)?

  NO Replace the engine board.

NO Check the cable connections, then replace the high-voltage power unit or belt cassette assembly. Did the printer recover?

  YES End.

NO Is the I/D unit terminal connected properly to the contact assembly. (See Fig. 5-2)

  NO Connect the I/D unit terminal properly to the contact assembly.

YES Replace the image drum unit.

Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
2. If EEPROM is not replaced, refer to section 3.2.2.

④ Solid lines or streaks appear in the vertical direction. (Black lines, color lines / black streaks, color streaks) (Fig. 5-2 Ⓓ)

• Is the LED head assembly connected properly to the connection board (Y73 PWB)?

    NO   Connect the LED head assembly to the connection board properly.

  YES   Check the cable connections, then replace the LED head assembly. Did the printer recover?

    YES End.

  YES   Check the cable connections, then replace the connection board (Y73 PWB). Did the printer recover?

    YES End

  NO   Is the engine board (K7N PWB) connected properly to the connection board (Y73 PWB)?

    NO   Connected the engine board properly to the connection board.

  YES   Check the cable connections, then replace the engine board (K7N PWB). Did the printer recover?

    YES End

  NO   Is the I/D terminal connected properly to the contact assembly? (See Fig. 5-3)

    NO   Connect the I/D terminal properly to the contact assembly.

  YES   Replace the image drum.

Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
2. If EEPROM is not replaced, refer to section 3.2.2.

⑤ Thick white lines / streaks or blurred color lines / streaks appear in the vertical direction (Fig. 5-2 Ⓕ)

• Is the LED head dirty?

    YES Clean the LED head.

  NO   Is the LED head assembly connected to the connection board (Y73 PWB) properly?

    NO   Connect the LED head assembly to the connection board (Y73 PWB) properly.

  YES   Check the cable connections, then replace the LED head assembly. Did the printer recover?

    YES End.

  NO   Check the cable connections, then replace the connection board (Y73 PWB). Did the printer recover?

    YES End

  NO   Is the engine board (K7N PWB) connected properly to the connection board (Y73 PWB)?

    NO   Connected the engine board properly to the connection board.

  YES   Check the cable connections, then replace the engine board (K7N PWB). Did the printer recover?

    YES End

  NO   Is the I/D terminal connected properly to the contact assembly? (See Fig. 5-3)

    NO   Connect the I/D terminal properly to the contact assembly.

  YES   Replace the image drum.

    Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
             2. If EEPROM is not replaced, refer to section 3.2.2.

⑥ Poor Fusing (Ink spreads or peels when touched with fingers**)**

• Is regulated paper being used?

    NO   Use regulated paper.

YES   Is the contact of the fuser unit connected properly?

    NO   Connect the contact of the fuser unit properly.

YES   Is the roller in the fuser unit dirty?

    YES Replace the fuser unit assembly.

NO   Is the PAPER THICKNESS (menu 1) selected correctly?
Light: 64 g/m^2 Medium Light: 64 to 74 g/m^2 Medium: 75 to 90 g/m^2
Medium Heavy: 91 to 104 g/m^2 Heavy: 105 to 120 g/m^2 Ultra Heavy 121 to 203 g/m^2 OHP

    NO   Set [Paper Thickness] properly.

YES   Is AC voltage output between CN connector pins 1 and 3 in the low-voltage power unit?

    NO   Replace the low-voltage power unit.

YES   Is the heat roller thermister resistance within the regulated value? (See Fig. 5-1)
(Approx. 190k-980kΩ in room temperature of 0-43 degrees Celsius.)

    NO   Replace the fuser unit.

YES   Is the back-up roller thermister resistance within the regulated value? (See Fig. 5-1)
    (Approx. 190k-980kΩ in room temperature of 0-43 degrees Celsius.)

    NO   Replace the fuser unit.

YES   Does the fuser temperature match the set temperature?
Check the fuser temperature in the LCD display of the engine maintenance mode.
Heat roller (upper)   : 145-155 degrees (5FH-6BH)
Back-up (lower) : 125-135 degrees (48H-53H)

    NO   Replace the fuser unit assembly.

YES   Replace the fuser unit assembly.

> ***Note:*** 1. Remove EEPROM from the old board and set it on the new board upon replacing the
>   engine board (K7N PWB).
>   2. If EEPROM is not replaced, refer to section 3.2.2.

⑦   Consistent abnormality (Figure 5.2-Ⓔ)

Consistency	Problem	Remedy
94.2 mm	Image Drum	Replace the ID unit.
63.6 mm	Developing Roller	Replace the ID unit.
57.8 mm	Toner Supply Roller	Replace the ID unit.
44.0 mm	Charge Roller	Replace the ID unit.
113.1 mm	Fuser Roller (Upper)	Replace the fuser unit.
	Fuser Roller (Lower)	Replace the fuser unit.
57.8 mm	Transfer Roller	Replace the belt cassette assembly.

Note: The life counter for the I/D unit, fuser unit, and belt cassette unit is reset automatically when the unit is replaced.

⑧ Color detaches.

• Is the LED head dirty?

　　YES Clean the LED head.

　NO　　Is the LED head assembly connected to the connection board (Y73 PWB) properly?

　　　NO　Check the connection cable between the LED head and connection board, then connect properly.

　YES　　Is +5V output to the following HEADPOW connector pins on the connection board (Y73 PWB)?
　　　　　+5V: Pin 1, 2, 3, 4, 5, 6

　　　YES Is +5V output to the each LED head assemblies on the connection board (Y73 PWB)?
　　　　　3 pin for YPOW connector : LED head assembly - yellow
　　　　　3 pin for MPOW connector : LED head assembly - magenta
　　　　　3 pin for CPOW connector : LED head assembly - cyan
　　　　　3 pin for KPOW connector : LED head assembly - black

　　　　　NO　Replace the connection board (Y73 PWB).

　　YES Check the cable connections, then replace the LED head assembly.

　NO　　Check the cable connections, then replace the low-voltage power unit. Did the printer recover?

　　　YES End.

　NO　　Is 34V output to the power connector on the engine board (K7N PWB)?
　　　　　+34V: Pin 12, 13, 14

　　　NO　Check the cable connections, then replace the low-voltage power unit.

　YES　　Is 34V output to the HVOLT connector pin 2 on the engine board (K7N PWB)?

　　　NO　Replace the engine board.

　YES　　Check the cable connections, then replace the high-voltage power unit or belt cassette assembly.

　　　YES End.

　NO　　Is the I/D unit terminal connected properly to the contact assembly. (See Fig. 5-3)

　　　NO　Connect the I/D unit terminal to the contact assemblyproperly .

　YES　　Replace the image drum.

　　Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
　　　　　　 2. If EEPROM is not replaced, refer to section 3.2.2.

⑨ Color irregularity

• [Toner Low] is displayed.

　　YES Refill toner. Did the printer recover?

　　YES End.

▼ NO Perform the color irregularity test in the engine maintenance mode.
　　　　Method: Enter the self-diagnostic mode (Level 1) in the engine maintenance mode.

```
DIAGNOSTIC MODE

XX.XX.XX
```

Press the ⓪ and ④ keys and enter the self-diagnostic mode (Level 2).

```
ENGINE DIAG LEVEL2


```

Press the ① key three times and display [REG ADJUST TEST].

```
REG ADJUST TEST


```

Press the ② key once and display [REG ADJUST EXECUTE].

```
REG ADJUST EXECUTE


```

Press the ③ key and execute auto adjustment for color irregularity. (The motor will start to rotate and adjustment for color irregularity will begin.)

▼ [OK] is displayed immediately with executing color irregularity adjustment. (Motor does not rotate.)

　　YES Error other than color irregularity has generated. Did color irregularity recover after the error was released?

　　YES End.

(A)

(A)

NO   [NG CALIBRATION LEFT /RIGHT] display.

YES Is the color irregularity sensor cover dirty?

YES: Faulty cleaning operation of the rear sensor cover due to the cleaning blade on the rear side of the shutter. Replace the shutter and sensor cover, and recover cleaning capability.

NO   Check the connection of the Z71 board (color irregularity board) connector, RSNS on the K7N board (engine board), and power connector. Did the printer recover after checking the connections?

YES End.

NO   Replace the Z71 board. Did the printer recover?

YES End.

NO   Replace the engine board. Did the printer recover?

YES End.

NO   Replace the cables for the Z71 board and engine board. Did the printer recover?

YES End.

NO   [DYNAMICRANGE LEFT /RIGHT] display.

YES Is the color irregularity sensor cover dirty?

YES Faulty cleaning operation of the rear sensor cover due to the cleaning blade on the rear side of the shutter. Replace the shutter and sensor cover, and recover cleaning capability.

NO   Is the open/close operation of the shutter abnormal?

YES Replace the shutter. Did the printer recover?

YES End.

NO   Replace the shutter open/close solenoid. Did the printer recover?

YES End.

NO   Replace the belt unit. Did the printer recover?

YES End.

NO   Replace the ID unit. Did the printer recover?

YES End.

(B)

(B)

• [Yellow/Magenta/Cyan Left/Right/Horizontal] display

    YES Replace the belt unit. Did the printer recover?

        YES End.

    NO   Replace the ID unit. Did the printer recover?

        YES End.

    NO   Is the gear abnormal? (Gear assembly such as I/D, multipurpose tray, belt unit, belt motor.)

        YES Replace the damaged gear assembly.

    NO   Is the LED head unit connected to the connection board (Y73 PWB) properly?

        NO   Connect the LED head unit to the connection board properly.

    YES Check the cable connections, then replace the LED head assembly. Did the printer recover?

        YES End.

    NO   Check the cable connections, then replace the connection board (Y73 PWB). Did the printer recover?

        YES End.

    NO   Is the engine board (K7N PWB) connected to the connection board (Y73 PWB) properly?

        NO   Connect the engine to the connection board properly.

    NO   Replace the engine board. Did the printer recover?

        YES End.

    NO   Is the I/D terminal connected to the contact assembly properly? (See Fig. 5-3)

        NO   Connect the I/D terminal to the contact assembly properly.

    YES Replace the image drum.

      Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
            2. If EEPROM is not replaced, refer to section 3.2.2.

⑩   Color irregularity compared with the original

•   Is the LED head lens dirty?

   YES Clean the LED head lens.

NO   Is the LED head assembly connected to the connection board (Y73 PWB) properly?

   NO   Check the cable between the LED assembly and connection board and connect properly.

YES   Is +5V output to the following HEADPOW connector pins on the connection board (Y73 PWB)?
         +5V: Pin 1, 2, 3, 4, 5, 6

   • YES Is +5V output to the each LED head assemblies on the connection board (Y73 PWB)?
           3 pin for YPOW connector : LED head assembly - yellow
           3 pin for MPOW connector : LED head assembly - magenta
           3 pin for CPOW connector : LED head assembly - cyan
           3 pin for KPOW connector : LED head assembly - black

         NO   Replace the connection board (Y73 PWB).

   YES Check the cable connections, then replace the LED head assembly.

NO   Check the cable connections, then replace the low-voltage power unit. Did the printer recover?

   YES End.

NO   Is 34V output to the power connector on the engine board (K7N PWB)?
         +34V: Pin 12, 13, 14

   NO   Check the cable connections, then replace the low-voltage power unit.

YES   Is 34V output to HVOLT connector pin 2 on the engine board (K7N PWB)?

   NO   Replace the engine board.

YES   Check the cable connections, then replace the high-voltage power unit or belt cassette assembly. Did the printer recover?

   YES End.

NO   Is the I/D unit terminal connected properly to the contact assembly. (See Fig. 5-3)

   NO   Connect the I/D unit terminal properly to the contact assembly.

YES   Replace the image drum unit.

   Note: 1. Remove EEPROM from the old board and set it on the new board upon replacing the engine board (K7N PWB).
           2. If EEPROM is not replaced, refer to section 3.2.2.

⑪ Paper thickness error (Err Code 323, 324)

• Is the sensor connector connected?

  NO Connect the connecter.

YES Is the sensor cable disconnected?

  NO Replace the cable.

YES Is +5V output to the PU board REG 13pin?

  NO Replace the PU board.

YES IS GND connection made to the PU board REG 15pin?

  NO Replace the PU board.

YES Is pulse signal 5ms ON 10% Duty output to the PU board REG 16pin?
     (Disabled on field due to sync usage.)

  NO Replace the PU board.

YES Turn ON the power and check the media thickness. Is the error released?

  NO Replace the sensor.

YES: End.

Ground

Charge Roller

Developing Roller

Toner Supply Roller

Figure 5.3

5.6   Fuse check

When it is occured bellow errors, check these fuses on Print Engine Controller PWB (K7N-PWB).

Table 5-6 Fuse Error

Fuse Name	Error Description	Insert Point
F1	2nd or 3rd or 4th or 5th TRY Hopping Error	Option TRY 34V
F2	MID UP/DOWN Error	MID,Hopping Motor Driver
F3	Fuse Cut Error	YID,Fuser Motor Driver JODEN-board
F4	JAM	KID,Registraiton Motor Driver
F5	CID UP/DOWN Error	CID,Belt Motor Driver
F6	POEWR OFF	5V Sensor
F7	PU FAN Error FAN Clutch	JobOff Motor Driver
F8	Cover Open	Cover Open Switch
F9	Lift Error (TRY1)	Geared Motor Driver

6. WIRING DIAGRAM

6.1 Resistance Check

| Unit	Circuit Diagram	Illustration	Resistance
Transfer Belt Motor	1 Yellow 2 Orange 3 Black 4 Brown		Between pins 1 and 2: 7.9Ω Between pins 3 and 4: 7.9Ω
Main Motor (Y)	1 2 3 4		Between pins 1 and 2: 2.4Ω Between pins 3 and 4: 2.4Ω
Main Motor (M)	1 2 3 4		Between pins 1 and 2: 2.4Ω Between pins 3 and 4: 2.4Ω

Unit	Circuit Diagram	Illustration	Resistance
Main Motor (C)			Between pins 1 and 2: 2.4Ω Between pins 3 and 4: 2.4Ω
Main Motor (B)			Between pins 1 and 2: 2.4Ω Between pins 3 and 4: 2.4Ω
MT Resistration Motor			Between pins 1 and 2: 7.9Ω Between pins 3 and 4: 7.9Ω

Unit	Circuit Diagram	Illustration	Resistance
Fuser Motor	M — Yellow 1, Orange 2, Black 3, Brown 4		Between pins 1 and 2: 7.9Ω Between pins 3 and 4: 7.9Ω
Feeder Motor	M — 1, 2, 3, 4		Between pins 1 and 2: 7.9Ω or 8.4Ω Between pins 3 and 4: 7.9Ω or 8.4Ω
Offset Motor	M — Yellow 1, Orange 2, Black 3, Brown 4		Between pins 1 and 2: 23Ω Between pins 3 and 4: 23Ω

Unit	Circuit Diagram	Illustration	Resistance
Geared Motor	CN-1 ⊖ M CN-2 ⊕		
CU Low-voltage Ejection Fuser Fan and Electrical Chassis Cooling Fan	M 1 Red +34 V 3 White FANALM-N 2 Black 0 V		
Low-voltage Absorption and Fuser Fan	M 1 Red +34 V 3 White FANALM-N 2 Black 0 V		

Unit	Circuit Diagram	Illustration	Resistance
Fuser Unit Exhaust Fan	Red 1 +34 V / White 3 FANALM-N / Black 2 0 V — M		
CU Board	Red 1 +5 V / White 3 FANALM-N / Black 2 0 V — M		
ID Fan	Red 1 +5 V / White 3 / Black 2 0 V — M		

| Unit	Circuit Diagram	Illustration	Resistance
Fuser Unit	① Upper roller — Heater, Thermostat①, Thermostat②, Thermistor, Thermistor Left ② Backup roller — Heater, Thermistor, Fuse a b c d e f	1. Upper roller side b a c d e f 2. Backup roller side	① Between pins a and b: Between pins c and d: 231.4k (at 25 °C) Between pins e and f: 231.4k (at 25 °C) ② Between pins a and b: Between pins c and d: 0 or open Between pins e and f: 231.4k (at 25 °C)

6.2   Parts Layout on Boards

(1)-1 Print Engine Controller PWB (K7N-3:PWB:600dpi)

(1)-2 Print Engine Controller PWB (K7N-4:PWB:1200dpi)

(2)　Main Controller PWB: TIG

FAN

PUIF

SDMM1

SDMM2

SDMM3

2xDIMM sockets
(for program and fonts)

3xDIMM sockets
(SDRAM DIMM (64MB~512MB))

DIMM

SDRAM

168

168

84 B

84 A

IDE

PCICU

A1
B1
C1

A36
B36
C36

EEPROM

18
36

1
19

2
3

1
4

CENT

USB

(3) LED Control PWB
a)(Y73-2 PWB:600dpi)

b)(Y7X-2 PWB:1200dpi)

(4) Duplex Control PWB (V73- PWB)

(5) Control Panel PWB (X7N- PWB)

(6) N71-PWB

JODEN

(7) Entrance Sensor PWB (R71- PWB)

INSNS2   INSNS1

FSNS

HUM

WRSNS

TNR

(8) Paper Size Sensing PWB (B73- PWB)

SW1   SW2   SW3   SW4

CN11

(9) Sensor PWB (A73-PWB)

LIFT

CN1

HOP

(10) Option I/F PWB (C73-PWB)

MAIN1
SAVIF

(11) Tray Control PWB (V73-PWB)

(12) Hight-Voltage PWB

(13) Low-voltage PWB

(14) Color Registration Sensor PWB (Side L:Z7L, Side R:Z7R)

(15) Humidity Sensor

(16) Density Sensor

7. PARTS LIST

Figure 7-1-1/3

Figure 7-1-2/3

Figure 7-1-3/3

Table 7-1-1/3

Main Assembly

| No.	Patrs No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41481203	Cover Assy-R	1	3	6	12	
2	41484915	Cassette Assy	1	3	6	12	ODA/OEL/APS
3	41353701	Cover-Front-CS	1	3	6	12	
4	41277901	Cover-Blank	1	3	6	12	
5	41276401	Cover-Front	1	3	6	12	OEL/APS
	41749602	Cover-Assy-Front	1	3	6	12	ODA
6	41277401	Cover-Side(L)	1	3	6	12	
7	41484201	Stacker-Face-Up Assy	1	3	6	12	
8	41276501	Cover-Rear	1	3	6	12	
9	41484603	Cover-Assy MT	1	3	6	12	
10	41493013	MPT Assy-713	1	3	6	12	OEL/APS
	41493014	MPT.Assy-713	1	3	6	12	ODA
11	41297101	Plate-Top	1	3	6	24	
12	40325101	Gear-Z68	2	6	12	12	
13	41764103	Frame-Assy-Top	1	3	6	12	OEL/APS
	41764102	Frame-Assy-Top	1	3	6	12	ODA
14	41960434	Print Engine Controller PWB	1	3	6	12	1200dpi
	41960432	Print Engine Controller PWB	1	3	6	12	600dpi
15	41490703	Motor-Fan(80)	1	3	6	12	
16	41275702	Microswitch-Assy	1	3	6	12	
17	4PB4083-2500P008	Screw (T3×8)	20	-	-	-	
18	4PB4013-3100P008	Screw (M3×8)	2	-	-	-	
19	4PB4083-2500P010	Screw (T3×10)	24	-	-	-	
20	8162303M0001	EEPROM	1	3	6	12	
21	4PB4013-3100P006	Screw (M3×6)	31	40	80	120	
22	41946101	Fuser-Unit	1	3	6	12	ODA(120V)
	41946105	Fuser-Unit	1	3	6	12	OEL
	41946109	Fuser-Unit	1	3	6	12	APS
	41946103	Fuser-Unit	1	3	6	12	ODA(230V)
23	41946001	Belt-Unit	1	3	6	12	ODA
	41946003	Belt-Unit	1	3	6	12	OEL
	41946009	Belt-Unit	1	3	6	12	APS

Table 7-1-2/3

No.	Patrs No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
24	41963401	ID-Y Type C5	1	-	-	-	ODA Consumable
	41963402	ID-M Type C5	1	-	-	-	ODA Consumable
	41963403	ID-C Type C5	1	-	-	-	ODA Consumable
	41963404	ID-K Type C5	1	-	-	-	ODA Consumable
	41963405	ID-Y Type C5	1	-	-	-	OEL Consumable
	41963406	ID-M Type C5	1	-	-	-	OEL Consumable
	41963407	ID-C Type C5	1	-	-	-	OEL Consumable
	41963408	ID-K Type C5	1	-	-	-	OEL Consumable
	41963409	ID-Y Type C5	1	-	-	-	APS Consumable
	41963410	ID-M Type C5	1	-	-	-	APS Consumable
	41963411	ID-C Type C5	1	-	-	-	APS Consumable
	41963412	ID-K Type C5	1	-	-	-	APS Consumable
25	41963601	Toner-Cartridge_Type_C5_Y	1	-	-	-	ODA Consumable
	41963602	Toner-Cartridge_Type_C5_M	1	-	-	-	ODA Consumable
	41963603	Toner-Cartridge_Type_C5_C	1	-	-	-	ODA Consumable
	41963604	Toner-Cartridge_Type_C5_K	1	-	-	-	ODA Consumable
	41963605	Toner-Cartridge_Type_C5_Y	1	-	-	-	OEL Consumable
	41963606	Toner-Cartridge_Type_C5_M	1	-	-	-	OEL Consumable
	41963607	Toner-Cartridge_Type_C5_C	1	-	-	-	OEL Consumable
	41963608	Toner-Cartridge_Type_C5_K	1	-	-	-	OEL Consumable
	41963609	Toner-Cartridge_Type_C5_Y	1	-	-	-	APS Consumable
	41963610	Toner-Cartridge_Type_C5_M	1	-	-	-	APS Consumable
	41963611	Toner-Cartridge_Type_C5_C	1	-	-	-	APS Consumable
	41963612	Toner-Cartridge_Type_C5_K	1	-	-	-	APS Consumable
	41963801	Toner-Cartridge_Type_C5_Y S	1	-	-	-	ODA
	41963802	Toner-Cartridge_Type_C5_M S	1	-	-	-	ODA
	41963803	Toner-Cartridge_Type_C5_C S	1	-	-	-	ODA
	41963804	Toner-Cartridge_Type_C5_K S	1	-	-	-	ODA
	41963805	Toner-Cartridge_Type_C5_Y S	1	-	-	-	OEL
	41963806	Toner-Cartridge_Type_C5_M S	1	-	-	-	OEL
	41963807	Toner-Cartridge_Type_C5_C S	1	-	-	-	OEL
	41963808	Toner-Cartridge_Type_C5_K S	1	-	-	-	OEL
	41963809	Toner-Cartridge_Type_C5_Y S	1	-	-	-	APS
	41963810	Toner-Cartridge_Type_C5_M S	1	-	-	-	APS
	41963811	Toner-Cartridge_Type_C5_C S	1	-	-	-	APS
	41963812	Toner-Cartridge_Type_C5_K S	1	-	-	-	APS

Table 7-1-3/3

No.	Patrs No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
26	41884009	PCB Assy-TIG-3	1	3	6	12	600dpi
	41884019	PCB Assy-TIG-2	1	3	6	12	1200dpi
27	8164323M0000	EEPROM(CU)	1	3	6	12	
28	42277504	Board-CRF(PX713[1200])	1	3	6	12	C9500
	42277508	Board-CRF(PX713[600])	1	3	6	12	C9300
29							
30	41437436	Board-Memory 64MB	1	3	6	12	APS Option
	41437437	Board-Memory 128MB	1	3	6	12	APS Option
	41437438	Board-Memory 256MB	1	3	6	12	APS Option
	41437441	Board-Memory 64MB	1	3	6	12	OEL Option
	41437442	Board-Memory 128MB	1	3	6	12	OEL Option
	41437443	Board-Memory 256MB	1	3	6	12	OEL Option
	41437446	Board-Memory 64MB	1	3	6	12	ODA Option
	41437447	Board-Memory 128MB	1	3	6	12	ODA Option
	41437448	Board-Memory 256MB	1	3	6	12	ODA Option
31	41705103	Oki LAN 6200et	(1)	(3)	(6)	(12)	ODA
	41997101	Oki LAN 7300e/MLETB11	(1)	(3)	(6)	(12)	ODA/OEL/APS
32	41376019	10GB HDD	(1)	(3)	(6)	(12)	
~~33~~	~~41964019~~	~~Board Assy.-CU(713)~~	~~1~~	~~3~~	~~6~~	~~12~~	~~1200dpi~~
	~~41964009~~	~~Board Assy.-CU(713)~~	~~1~~	~~3~~	~~6~~	~~12~~	~~600dpi~~
34	41278601	Guide -Rail(A)	2	6	12	28	
35	41278701	Guide -Rail(B)	1	3	6	12	
36	41410201	Motor-Fan	1	3	6	12	
37	41467401	Plate-FG(Centro)	1	3	6	12	
38	41254601	Plate-blank	2	6	12	28	
39	41723901	Screw	4	-	-	-	
40							
41	41366501	Limitter-2Way(Front)	1	3	6	12	
42	41366601	Limitter-2Way(Rear)	1	3	6	12	
43							
44	1050003C0006	TFC-20/TFT-102010	1	3	6	12	Core LAN Cable

Figure 7-2

Table 7-2

Top Cover Assembly

| No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41484401	Cover Assy-Stacker	1	3	6	12	
2	42461201	LED Head 1200dpi Kit	4	12	24	48	1200dpi
	42461101	LED Head 600dpi Kit	4	12	24	48	600dpi
3	42459501	LED Assy Spring	8	24	48	96	
4	42124802	LED control PWB	1	3	6	12	1200dpi
	41960902	LED control PWB	1	3	6	12	600dpi
5	41349801	Lever Stack Full	1	3	6	12	
6	41487106	Cover Assy-Inn(Sub)	1	3	6	12	OEL/APS
	41487108	Cover Assy-Inn(Sub)	1	3	6	12	ODA
7	42169501	LED Harness K	1	3	6	12	600dpi
8	42169502	LED Harness Y	1	3	6	12	600dpi
9	42169503	LED Harness M	1	3	6	12	600dpi
10	42169504	LED Harness C	1	3	6	12	600dpi
11	41703701	Sensor Assy Toner	4	12	24	48	
12	41484504	Control Panel Assy	1	3	6	12	
13	40866220	OP Panel					
	52518703	label					ES3037
	52518704	label					ES3037E
	52519801	lable					Oki label
14	2381003P0018	Control Panel Tape Harness	1	3	6	12	600dpi
	2381003P0031	Control Panel Tape Harness	1	3	6	12	1200dpi
15	41947901	Eject Guide Assy	1	3	6	12	
16	42167801	Cord Assy Head	1	3	6	12	1200dpi
17	41454403	Motor-Fan(80-25)	1	3	6	12	
18	4PB4083-2500P008	Screw(T3×8)	19	-	-	-	
19	40197105	Motor-Fan(CU)	1	3	6	12	
20	2381021P0020	LED Harness	4	12	24	48	1200dpi
21	2381021P0021	LED Harness	4	12	24	48	1200dpi
22	42174701	LED Control PWB Tape Harness	1	3	6	12	600dpi
23	42447501	Post-guide	8	24	48	96	

Figure 7-3-1/2

Figure 7-3-2/2

Table 7-3-1/2

Printer Unit Chassis

No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41189701	Drum contact Assy	4	12	24	48	
2	41483206	Registration Roller Assy (A)	1	3	6	12	
3	41483301	Registration Roller Assy (B)	1	3	6	12	
4	41628401	Registration Drive Gear (A)	1	3	6	12	
5	41187102	Registration Clutch	1	3	6	12	
6	41483406	Registration Motor Assy	1	3	6	12	
7	41483702	Motor-Assy-Fan (PULL)	1	3	6	12	
8	41947801	Color Registration Sensor Assy	1	3	6	12	
9	41744006	Solenoid-Shutter Assy	1	3	6	12	
10	41947701	Plate-Shutter A3 (Adhesive)	1	3	6	12	
11	42030001	Spring-Shutter A3	1	3	6	12	
12	41486801	Duplex Guide Assy	1	3	6	12	
13	41941501	Printer Unit Chassis	1	3	6	12	OEL/APS
	41941503	Printer Unit Chassis	1	3	6	12	ODA
14							
15							
16	40841601	Entrance Cassette Sensor Actuator	1	3	6	12	
17	41578501	Entrance MT Sensor Actuator	1	3	6	12	
18	40841801	Entrance Belt Sensor Actuator	1	3	6	12	
19	41258301	Board R71 (Entrance Sensor PWB)	1	3	6	12	
20	41486601	Magnet-Assy-Dup	1	3	6	12	
21	41393901	Solenoid Sheet Assy	1	3	6	12	
22	41095901	Roller Feed(C)	1	3	6	12	
23	4PP4076-3949P001	Fuser Exit Roller Bushing (L)	1	3	6	12	
24	4PP4043-4489P001	Fuser Exit Roller Bushing (R)	1	3	6	12	
25	41073602	Exit Sensor Assy	1	3	6	12	
26	40841301	Fuser Latching Handle (L)	1	3	6	12	
27	41628301	Fuser Latching Handle Spring	2	6	12	24	
28	41483906	Transfer Belt Motor Assy	1	3	6	12	
29	40841401	Fuser Latching Handle (R)	1	3	6	12	
30	41483806	Main Motor Assy	1	3	6	12	
31	41484001	Left Plate Assy	2	6	12	24	
32	40850206	Contact Assy	1	3	6	12	
33	41863002	PWR Unit-ACDC Switch 120V	1	3	6	12	
	41870802	PWR Unit-ACDC Switch 230V	1	3	6	12	
34	42046801	Power Unit(High-Voltage)	1	3	6	12	

Table 7-3-2/2

No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
35	2381023P0004	HV Tape Harness	1	3	6	12	
36	41500101	Power Supply Insulation	1	3	6	12	
37	4PB4013-3100P006	Screw (M3×6)	26	-	-	-	
38	PSW4-8C	Screw (M4×8)	1	-	-	-	
39	4PB4083-2500P008	Screw (T3×8)	29	-	-	-	
40	41346301	Transfer Contact Assy	2	6	12	24	
41	41589501	Power Supply Insulation(HV)	1	3	6	12	
42	40197103	Motor-Fan(PUSH)	1	3	6	12	
43	41431602	Motor-ID Fan	1	3	6	12	
44							
45	5632001P0001	Thickness Sensor	1	3	6	12	
46	41886901	Thickness Plate Assy	1	3	6	12	
47	41911101	Thickness Sensor Assy	1	3	6	12	
48	41888701	Cover Seal Sensor	1	3	6	12	
49	41928801	Pickup Stage	1	3	6	12	
50	42199601	Waste Toner Sensor Actuator	1	3	6	12	

Figure 7-4-1/2

Figure 7-4-2/2

Table 7-4

Paper Tray Guide

No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41481306	Guide-Assy-R-1st	1	3	6	12	
2	41766501	Roller-Feed	3	9	18	36	
3	41488401	Roller-Feed-A3	1	3	6	12	
4	41880101	Motor-Pulse(Hop)	1	3	6	12	
5	41515701	Board-A73	1	3	6	12	
6	41503001	Gear.Assy-Clutch(2pin)	1	3	6	12	
7	41502601	Rubber Foot	4	12	24	48	
8	41950401	Paper Size Sensing PWB	1	3	6	12	
9	2201000P0140	Connector	2	6	12	24	
10	4PB4013-3101P006	Screw (T4×6)	4	-	-	-	
11	4PB4013-3101P008	Screw (T4×8)	27	-	-	-	
12	4PB4013-3100P008	Screw (M3×8)	18	-	-	-	
13	4PB4083-2500P010	Screw (T3×10)	4	-	-	-	
14							
15	PSW2W3-10C	Screw	2	-	-	-	
16	PSW2W3-16C	Screw	1	-	-	-	
17	PSW2W3-20C	Screw	3	-	-	-	
18	41488301	Gear.Assy-Clutch(3pin)	1	3	6	12	
19							
20							
21							
22							
23							
24							
25							
26	41487801	Motor-Geard	1	3	6	12	

Figure 7-5

Table 7-5

Duplex Unit

No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41945701	Duplex Unit	1	-	-	-	ODA
	41945703	Duplex Unit	1	-	-	-	OEL
	41945707	Duplex Unit	1	-	-	-	APS
2	4PB4043-4718P001	Screw (SP3×10)	2	-	-	-	
3	4PB4083-2500P008	Screw (T3×8)	21	-	-	-	
4	4PB4013-3100P006	Screw (M3×6)	9	-	-	-	

APPENDIX A INTERFACE SPECIFICATIONS

### 1. Parallel Interface Specifications

1.1 Parallel Interface

Item	Description
Mode	Compatibility mode, Nibble mode, ECP mode
Data bit length	8 bits: Compatibility mode, 4bits: Nibble mode,9 bits: ECP mode

1.2 Parallel Interface Connector and Cable

1) Connector
Printer side: 36-pin receptacle
Type 57LE-40360-12 (D56) (made by Daiichi Denshi) or equivalent
Cable side: 36-pin plug
Type 57FE-30360-20N (D8) (made by Daiichi Denshi) or equivalent

Connector Pin Arrangement Viewed from Cable Side

2) Cable
Cable length: 1.8 m max.
(A shielded cable composed of twisted pair wires is recommended for noise prevention.)

1.3 Parallel Interface Level

LOW: 0 V to +0.8 V
HIGH: +2.4 V to 5.0 V

1.4   Timing Charts

Compatible mode

a) Data receiving timing

PARALLEL DATA
(DATA BITs 1 to 8)

0.5 μs min.   0.5 μs min.

$\overline{\text{nStrobe}}$

0.5 μs min.

0.5 μs min.

0.5 μs max.

BUSY

0 min.

$\overline{\text{nAck}}$

0 min.

0.5 μs to 3 μs

0 min.

b) On-line (off-line switching timing by ON-LINE SW)

ON-LINE SW

BUSY

SELECT

100 ms max.

c) Off-line (on-line switching timing by ON-LINE SW)

ON-LINE SW

BUSY

SELECT
$\overline{\text{ACKNOWLEDGE}}$

d) nInit timing (invalid by default)

* Menu-set

50 μs min.

$\overline{\text{INPUT. PRIME}}$

BUSY

SELECT

5μs max.

$\overline{\text{ACKNOWLEDGE}}$

1.5   Parallel I/F Signals

Table 8-1 shows interface signal names and pin numbers.

Table 8-1 Signals

Pin No.	Signal Name	Signal Direction	Functions
1	Nstrobe (HostClk)	→PR	Pulse for reading data in at trailing edge.
2	DATA 1		
3	DATA 2		
4	DATA 3		8-bit parallel data.
5	DATA 4	→PR	Each signal is HIGH when data is logical 1 and
6	DATA 5		LOW when it is logical 0.
7	DATA 6		
8	DATA 7		
9	DATA 8		
10	nAck (PtrClk)	←PR	Indicates the completion of data reception.
11	Busy (PtrBusy)	←PR	Indicates whether the printer is ready for receiving data. Data cannot be received while the signal is HIGH.
12	PError (AckDataReq)	←PR	Indicates paper error when held HIGH.
13	Select (Xflag)	←PR	HIGH without exception when the parallel interface is enabled.
14	NAutoFd (HostBusy)	→PR	Used in bidirectional communication.
15	-		Unassigned.
16	GND		Signal ground.
17	FG		Chassis ground.
18	+5V	←PR	Used for supplying +5V. Power cannot be supplied to the outside of the printer.
19 ~ 30	GND		Signal ground.
31	NInit (nInit)	→PR	Initializes the printer when held LOW.
32	NFault (nDataAvail)	←PR	LOW during alarm.
33	GND		Signal ground.
34	-		Unassigned.
35	HILEVEL	←PR	Pulled up to +5V at 3.3KΩ inside the printer.
36	Nselectin (IEEE 1284 active)	→PR	Used in bidirectional communication. Low without exception in compatible mode.

Note: Parenthesized signal names are used in nibble mode.

Only functions in compatible mode are listed.

The C9300/C9500 series of printers supports the IEEE std 1284-1994 nibble mode. Note that, when used with personal computers or cables that do not comply with the standards, the printers may exhibit unpredictable behavior.

## 2.   Universal Serial Bus (USB) Interface Specifications

2.1   USB Interface

(1) Basic specifications
Conforms to USB specification, revision 1.1.
(2) Transmission mode
Full speed (max. 12 Mbps + 0.25%)
(3) Power Control
Self-power device

2.2   USB Interface Connector and Cable

(1) Connector
Printer side: Type B receptacle
Upstrem port
UBB-4R-D14T-1 (made by JST) or equivalent

Connector pin layout

Cable side: Type B plug

(2) Cable
Cable length: 5 m max. (cable compliant with USB specification, revision 1.1)
(A shielded cable must be used.)

2.3   USB Interface Signals

	R1	Function
1	Vbus	Power Supply (+5V) (red)
2	D -	Data transmission (white)
3	D +	Data transmission (green)
4	GND	Signal ground (black)
Shell	Shield	

APPENDIX B 2ND/3RD TRAY, HIGHT CAPACITY TRAY UNIT

2nd Tray

1. Control PWB, Paper Size Sensor PWB.

   (1) Unscrew the five screws ① to remove the cover-rear-opt ②.

   (2) Unscrew the four screws ③ to remove the cover-side (L)-opt ④.

   (3) Unscrew the two screws ⑤ to remove the cover-side (R) sub-opt ⑥.

   (4) Unscrew the screw ⑦ to remove the stopper ⑧, and disengage the front claw, to remove the cover Assy.-R ⑨.

   (5) Remove the ten screws ⑩ and the connector to remove the plate top ⑪.

   (6) Remove the all connectors and the four screws ⑫ to demount the control PWB ⑬.

   (7) Unscrew the four screws ⑭ to demount the paper size sensor PWB ⑮.

2. Motor-Geared

    (1) Unscrew the five screws ① to remove the great grip R ②.

    (2) Remove the six screws ③ to remove the feed unit ④.

    (3) Remove the three screws ⑤ to demount the motor-geared ⑥.

3. Transport Clutch

    (1) Remove the motor-geared (see section 2).

    (2) Unscrew the four screws ① to remove the motor Assy ②.

    (3) Remove the E ring ③ to detach the transport clutch ④.

4. Pickup Clutch

    (1) Remove the geared motor (see section 2).

    (2) Unscrew the four screws ① to remove the motor Assy ②.

    (3) Detach the pickup clutch ③.

5. Roller-Feed

    (1) Remove the geared motor (see section 2).

    (2) Unscrew the two screws ① to remove the feed Assy ②.

    (3) Unscrew the screw ③, remove the pillar sub ④, then detach the roller-feed ⑤.

6. Sensor PWB

    (1) Remove the geared motor (see section 2).

    (2) Unscrew the two screws ① to remove the feed Assy ②.

    (3) Remove the parts in the portion A and then in B and pull out the shaft ③ to remove the portion C.

    (4) Remove the sensor lever ④ to demount the sensor PWB ⑤.

Portion A

Remove the portion C

Portion B

7. High Capacity Tray Unit

    (1) Remove all the cassettes ①.

    (2) Unscrew the five screws ② to remove the cover-rear- pt ③.

    (3) Unscrew the four screws ④ to remove the cover-side (L)-opt ⑤.

    (4) Unscrew the two screws ⑥ to remove the cover-side (R) sub-opt ⑦.

    (5) Unscrew the four screws ⑧ to separate the first and second unit.

    (6) Unscrew the four screws ⑨ to separate the second and third unit.

    (7) Lift the tray unit upward to demount it.

High Capacity Tray Unit, 2nd/3rd Tray Unit (1/3)

High Capacity Tray Unit, 2nd/3rd Tray Unit (2/3)

Not attached to the lowest (thir

High Capacity Tray Unit, 2nd/3rd Tray Unit (3/3)

High Capacity Tray Unit, 2nd/3rd Tray Unit

No.	Parts No.	Name	Q'ty /Unit	Recommended Q'ty/Year			Remarks
				per 500	per 1000	per 2000	
1	41949401	Guide Assy.-(R)-Opt	1	3	6	12	2nd tray,1st/2nd unit of HCF
	41949403	Guide Assy.-(R)-Opt	1	3	6	12	3rd unit of HCF
2	41766501	Roller-Feed	3	9	18	36	
3	41488401	Roller-Feed (A3)	1	3	6	12	
4	41880201	Motor-Pulse (Hop)	1	3	6	12	
5	41515701	Board-A73	1	3	6	12	
6	41503001	Gear Assy.-Clutch	1	3	6	12	
7	41502601	Rubber-Foot	4	12	24	48	
8							
9	2201000P0140	Connector	1	3	6	12	
10	4PB4013-3101P006	Screw (T4×6)	4	-	-	-	
11	4PB4013-3101P008	Screw (T4×8)	27	-	-	-	
12	4PB4013-3100P008	Screw (M3×8)	18	-	-	-	
13	4PB4083-2500P010	Screw (T3×10)	4	-	-	-	
14							
15	PSW2W3-10C	Screw	2	-	-	-	
16	PSW2W3-16C	Screw	1	-	-	-	
17	PSW2W3-20C	Screw	3	-	-	-	
18	41488301	Gear Assy.-Clutch	1	3	6	12	
19	41547815	Cassette Assy.-Opt	1	3	6	12	OEL/APS
	41547816	Cassette Assy.-Opt	1	3	6	12	ODA
20	41503601	Cover-Side (L)-Opt	1	3	6	12	
21	41503801	Cover-Rear-Opt	1	3	6	12	
22	41780306	Board-V7X	1	3	6	12	
23	41950401	Board-B73	1	3	6	12	
24	41503701	Cover-Side (R) Sub-Opt	1	3	6	12	
25	41546505	Cover Assy.-R	1	3	6	12	2nd tray,1st/2nd unit of HCF
	41546503	Cover Assy.-R	1	3	6	12	3rd unit of HCF
26	2201000P0141	Connector	1	3	6	12	
27	41487801	Motor-Geard	1	3	6	12	
28	41547701	Castor	4	12	24	48	

APPENDIX C ES2024/2024E/ES3037/3037e SERIES ERROR MESSAGES

1.ES2024/2024E/ES3037/3037e Series (Error messages)

(Caution) * : Raise in the factory mode only.

** : Not raise in the standard config machines.

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
300	POWER OFF/ON 300:NETWORK ERROR	OFF	Blink	A network error is occurring.	
310	CLOSE COVER 310:UPPER COVER OPEN	OFF	Blink	The cover is open.	
311	CLOSE COVER 311:SIDE COVER OPEN	OFF	Blink	The cover is open.(PX711)	
311	CLOSE COVER 311:SIDE COVER OPEN	OFF	Blink	The cover is open.(PX713)	
312	CLOSE COVER 312:TRAY2 COVER OPEN	OFF	Blink	The cover is open.	
313	CLOSE COVER 313:TRAY3 COVER OPEN	OFF	Blink	The cover is open.	
314	CLOSE COVER 314:TRAY4 COVER OPEN	OFF	Blink	The cover is open.	
315	CLOSE COVER 315:TRAY5 COVER OPEN	OFF	Blink	The cover is open.	
320	CHECK FUSER UNIT 320:FUSER UNIT MISSING	OFF	Blink	The fuser unit is not correctly installed	
321	POWER OFF AND WAIT FOR A WHILE 321:MOTOR OVERHEAT	OFF	Blink	Motor (Driver LSD) overheat error	
323	OPEN AND CLOSE COVER 323:PAPER THICK ERROR	OFF	Blink	A Sensor output at Medea Empty is outside the spec.(factory mode only raise)	Anomalies with Media Weight Detection sensor.
324	OPEN AND CLOSE COVER 324:PAPER THICK ERROR	OFF	Blink	The difference among Sensor outputs is outside the spec.(factory mode only raise)	
325	OPEN AND CLOSE COVER 325:PAPER THICK ERROR	OFF	Blink	Media detected values are outside the spec.	
326	OPEN AND CLOSE COVER 326:PAPER THICK ERROR	OFF	Blink	Media detected values in U-Heavy Mode are outside the spec.	
327 *	DOWNLOAD CHIP DATA 327:DENSITY CALIBRATION CHIP ERROR	OFF	Blink	Density Adjustment's calibration chip correction errorOmission of factory default setting. To prevent setting mistake.Error that does not occur at user level.Displayed only in Factory Mode.	

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
330	CHECK BELT UNIT 330:BELT UNIT MISSING	OFF	Blink	The belt unit is not correctly installed.	
340	CHECK IMAGE DRUM 340:YELLOW DRUM MISSING	OFF	Blink	The drum is not correctly installed.	
341	CHECK IMAGE DRUM 340:MAGENTA DRUM MISSING	OFF	Blink		
342	CHECK IMAGE DRUM 340:CYAN DRUM MISSING	OFF	Blink		
343	CHECK IMAGE DRUM 340:BLACK DRUM MISSING	OFF	Blink		
350	INSTALL NEW IMAGE DRUM 350:YELLOW DRUM LIFE	OFF	Blink	The life of the drum (Alarm) Warning status takes effect at Cover Open/Close, while allowing 500 pages printing at maximum	
351	INSTALL NEW IMAGE DRUM 351:MAGENTA DRUM LIFE	OFF	Blink		
352	INSTALL NEW IMAGE DRUM 352:CYAN DRUM LIFE	OFF	Blink		
353	INSTALL NEW IMAGE DRUM 353:BLACK DRUM LIFE	OFF	Blink		
355	INSTALL NEW BELT UNIT 355:BELT UNIT LIFE	OFF	Blink	Notifies the transfer belt has reached its life.This is the error displayed based on the counter to indicate that the belt has reached its life, and printing will stop.	
356	INSTALL NEW BELT UNIT 356:BELT UNIT LIFE	OFF	Blink	Notifies the transfer belt has reached its life.This is the error to indicate that the belt has reached its life because the waste toner has filled up the container, and printing will stop.	
360	INSTALL DUPLEX UNIT 360:DUPLEX UNIT OPEN	OFF	Blink	Duplex unit is open (removed). When this error is detected, printing stops.(PX713 only)	
361	REMOVE FINISHER 361:PAPER JAM	OFF	Blink	Jam has occurred nearby FINISHER unit.(Only install the FINISHER unit) 361:Before Input 362:Input Area 363:Regist Roller 364:Invert Path 365:Invert Stack 366:Output Bin1 Exit 367:Output Bin2 Exit	
362	REMOVE FINISHER 362:PAPER JAM	OFF	Blink		
363	REMOVE FINISHER 363:PAPER JAM	OFF	Blink		
364	REMOVE FINISHER 364:PAPER JAM	OFF	Blink		
365	REMOVE FINISHER 365:PAPER JAM	OFF	Blink		
366	REMOVE FINISHER 366:PAPER JAM	OFF	Blink		
367	REMOVE FINISHER 367:PAPER JAM	OFF	Blink		

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
370	CHECK DUPLEX 370:PAPER JAM	OFF	Blink	Jam has occurred nearby DUPLEX unit.(Duplex Reversal)	
371	CHECK DUPLEX 371:PAPER JAM	OFF	Blink	Jam has occurred nearby DUPLEX unit.(Duplex Input)	
372	CHECK DUPLEX 372:PAPER JAM	OFF	Blink	Jam has occurred nearby DUPLEX unit.(Duplex Missfeed)	
380	OPEN FRONT COVER 380:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(PX711)	
380	OPEN FRONT COVER 380:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(PX713)	
381	OPEN UPPER COVER 381:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(Transport)	
382	OPEN UPPER COVER 382:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(Exit)	
383	OPEN UPPER COVER 383:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(Duplex Entry)	
389	OPEN UPPER COVER 389:PAPER JAM	OFF	Blink	Jam has occurred in paper path.(Others)	
390	CHECK MPTRAY 390:PAPER JAM	OFF	Blink	Paper jam occurred during paper feeding from each tray.	
391	CHECK TRAY1 391:PAPER JAM	OFF	Blink		
392	CHECK TRAY2 392:PAPER JAM	OFF	Blink		
393	CHECK TRAY3 393:PAPER JAM	OFF	Blink		
394	CHECK TRAY4 394:PAPER JAM	OFF	Blink		
395	CHECK TRAY5 395:PAPER JAM	OFF	Blink		
400	OPEN UPPER COVER 400:PAPER SIZE ERROR	OFF	Blink	Inappropriate size paper was fed from a tray. Check the paper in the tray or check for Multiple-feed. Open and close the cover to perform recovery printing, and continue.	
401	OPEN UPPER COVER 401:PAPER MULTI FEED	OFF	Blink	Warns that inappropriate long paper has been fed from the tray. Check whether Multi-feed has happened. Recovery Print takes place at Cover Open/Close, allowing the operation to continue.	

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
410	INSTALL NEW TONER 410:YELLOW TONER EMPTY	OFF	Blink	Toner of (Yellow/Magenta/Cyan/Black) ends. Warning status takes effect at Cover Open/Close, while allowing printing at least 20 pages	
411	INSTALL NEW TONER 411:MAGENTA TONER EMPTY	OFF	Blink		
412	INSTALL NEW TONER 412:CYAN TONER EMPTY	OFF	Blink		
413	INSTALL NEW TONER 413:BLACK TONER EMPTY	OFF	Blink		
420	INSTALL ADDITIONAL MEMORY 420: MEMORY OVERFLOW	OFF	Blink	Memory capacity overflows due to the following reason. Press ON-LINE switch so that it continues. Install expansion RAM or decrease the data amount. - Too much print data in a page. - Too much Macro data. - Too much DLL data. - After frame buffer compress	
430	INSTALL PAPER CASSETTE 430:TRAY1 MISSING	OFF	Blink	The tray cassette of paper to which printing is intended is removed, and paper cannot be fed.	
431	INSTALL PAPER CASSETTE 431:TRAY2 MISSING	OFF	Blink		
432	INSTALL PAPER CASSETTE 432:TRAY3 MISSING	OFF	Blink		
433	INSTALL PAPER CASSETTE 433:TRAY4 MISSING	OFF	Blink		
434	INSTALL PAPER CASSETTE 434:TRAY5 MISSING	OFF	Blink		
440	INSTALL PAPER CASSETTE 440:TRAY1 OPEN	OFF	Blink	The tray cassette that is a paper path for the paper to be printed to is removed.(PX711 only)	
441	INSTALL PAPER CASSETTE 441:TRAY2 OPEN	OFF	Blink		
442	INSTALL PAPER CASSETTE 442:TRAY3 OPEN	OFF	Blink		
443	INSTALL PAPER CASSETTE 443:TRAY4 OPEN	OFF	Blink		
440	INSTALL PAPER CASSETTE 440:TRAY1 OPEN	OFF	Blink	The tray cassette that is a paper path for the paper to be printed to is removed.(PX711 only)	
441	INSTALL PAPER CASSETTE 441:TRAY2 OPEN	OFF	Blink		
442	INSTALL PAPER CASSETTE 442:TRAY3 OPEN	OFF	Blink		
443	INSTALL PAPER CASSETTE 443:TRAY4 OPEN	OFF	Blink		Not rasise (TRAY4:not configuration)

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
450	REMOVE THE PAPER 450:TRAY1 UNSUITABLE SIZE	OFF	Blink	Paper that cannot be used in the tray is set. (It takes a while until the status appears after you have closed the tray and the lever lifted.)	
451	REMOVE THE PAPER 451:TRAY2 UNSUITABLE SIZE	OFF	Blink		
452	REMOVE THE PAPER 452:TRAY3 UNSUITABLE SIZE	OFF	Blink		
453	REMOVE THE PAPER 453:TRAY4 UNSUITABLE SIZE	OFF	Blink		
454	REMOVE THE PAPER 454:TRAY5 UNSUITABLE SIZE	OFF	Blink		
460	CHANGE PAPER TO mmmmmmmmm/ppppppp 460:MPTRAY MEDIA MISMATCH	OFF	Blink	The size of paper or media type in the tray does not match the print data. Load mmmmm/ppppp paper in the tray (It takes a while until the status disappears after you have closed the tray and the lever lifted.) mmmmm : Paper Size (A4 , . ,B5 ,A6) pppp	
	CHANGE PAPER TO mmmmmmmmm/ppppppp 460:MPTRAY SIZE MISMATCH	OFF	Blink		
461	CHANGE PAPER TO mmmmmmmmm/ppppppp 461:TRAY1 MEDIA MISMATCH	OFF	Blink		
	CHANGE PAPER TO mmmmmmmmm/ppppppp 461:TRAY1 SIZE MISMATCH	OFF	Blink		
462	CHANGE PAPER TO mmmmmmmmm/ppppppp 462:TRAY2 MEDIA MISMATCH	OFF	Blink		
	CHANGE PAPER TO mmmmmmmmm/ppppppp 462:TRAY2 SIZE MISMATCH	OFF	Blink		
463	CHANGE PAPER TO mmmmmmmmm/ppppppp 463:TRAY3 MEDIA MISMATCH	OFF	Blink		
	CHANGE PAPER TO mmmmmmmmm/ppppppp 463:TRAY3 SIZE MISMATCH	OFF	Blink		
464	CHANGE PAPER TO mmmmmmmmm/ppppppp 464:TRAY4 MEDIA MISMATCH	OFF	Blink		
	CHANGE PAPER TO mmmmmmmmm/ppppppp 464:TRAY4 SIZE MISMATCH	OFF	Blink		

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
465	CHANGE PAPER TO mmmmmmmmm/ppppppp 465:TRAY5 MEDIA MISMATCH	OFF	Blink	The size of paper or media type in the tray does not match the print data. Load mmmmm/ppppp paper in the tray (It takes a while until the status disappears after you have closed the tray and the lever lifted.)	
	CHANGE PAPER TO mmmmmmmmm/ppppppp 465:TRAY5 SIZE MISMATCH	OFF	Blink		
469 **	(Reserved : for FRONT FEEDER)	OFF	Blink	mmmmm : Paper Size (A4 , . ,B5 ,A6) pppp	
	(Reserved : for FRONT FEEDER)	OFF	Blink		
471	CHECK STAPLER CARTRIDGE 471:STAPLER CARTRIDGE MISSING	OFF	Blink	The stapler cartridge of Finisher unit is removed	
472	CHECK PUNCH CHIP BOX 472:PUNCH CHIP BOX MISSING	OFF	Blink	The punch chip box of Finisher unit is removed	
473	INSTALL FINISHER 473:FINISHER IS REMOVED	OFF	Blink	The finisher unit is removed	
480	REMOVE THE PAPER 480:STACKER FULL	OFF	Blink	Stacker-full is occurring in the upper part of the printer.	
481	REMOVE THE PAPER 481:FINISHER STACKER FULL	OFF	Blink	Stacker-full in the finisher is occurring.	
482	REMOVE THE PAPER 482:FINISHER STACKER FULL	OFF	Blink	Stacker-full in the finisher is occurring.	
490	LOAD mmmmmmmmm 490:MPTRAY EMPTY	OFF	Blink	Printing request is issued to the empty tray. Load mmmmmmmmm paper. (It takes a while until the status disappears after you have closed the tray and the lever lifted.)	
491	LOAD mmmmmmmmm 491:TRAY1 EMPTY	OFF	Blink		
492	LOAD mmmmmmmmm 492:TRAY2 EMPTY	OFF	Blink	mmmmmmmmm : Paper Size (A4 ,,,B5, A6)	
493	LOAD mmmmmmmmm 493:TRAY3 EMPTY	OFF	Blink		
494	LOAD mmmmmmmmm 494:TRAY4 EMPTY	OFF	Blink		
495	LOAD mmmmmmmmm 495:TRAY5 EMPTY	OFF	Blink		
499 **	(Reserved : for FRONT FEEDER)	OFF	Blink		
500	SET mmmmmm ON MPTRAY AND PUSH ON-LINE SWITCH	Light	OFF	Manual paper feed is required. Manually insert the paper shown by mmmmm. mmmmmmmmm :Paper Size (A4 ,,,B5, A6)	

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
520	CHECK PAPER CASSETTE 520:TRAY1 LIFT UP ERROR	OFF	Blink	Print request was made to Tray1~5, to which Tray Lift Up Error has occurred. Lift Up Retry will take place when the tray is removed and put back in. (PX713 only)	
521	CHECK PAPER CASSETTE 521:TRAY2 LIFT UP ERROR	OFF	Blink		
522	CHECK PAPER CASSETTE 522:TRAY3 LIFT UP ERROR	OFF	Blink		
523	CHECK PAPER CASSETTE 523:TRAY4 LIFT UP ERROR	OFF	Blink		
524	CHECK PAPER CASSETTE 524:TRAY5 LIFT UP ERROR	OFF	Blink		
530	REMOVE EXCESS PAPER 530:TRAY1 OVERFILLED	OFF	Blink	Print request was made to Tray 1~5, which has been detected to have too much paper. This status will be cleared when excess paper is removed from that tray and the tray is put back in. (PX713 only)	
531	REMOVE EXCESS PAPER 531:TRAY2 OVERFILLED	OFF	Blink		
532	REMOVE EXCESS PAPER 532:TRAY3 OVERFILLED	OFF	Blink		
533	REMOVE EXCESS PAPER 533:TRAY4 OVERFILLED	OFF	Blink		
534	REMOVE EXCESS PAPER 534:TRAY5 OVERFILLED	OFF	Blink		

2.ES2024/2024E/ES3037/3037e Series (Error messages : Related to Color, Media Detect)

(Caution)　* : Raise in the factory mode only.

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
	_ COLOR ADJUSTING	Varies	Varies	Executing Auto Color Adjusting	
	_ DENSITY ADJUSTING	Varies	Varies	Executing Auto Density Adjustment	
	_ MEDIA WEIGHT DETECTING	Varies	Varies	Detecting media weight.	
	_ YELLOW TONER SENSOR ERROR	Varies	Light	Something is wrong with the toner sensor. When the Engine setting is Shipping mode, displayed in a combination of other message in the first line. If the engine setting is Factory mode, error display appears as mentioned later	
	_ MAGENTA TONER SENSOR ERROR	Varies	Light		
	_ CYAN TONER SENSOR ERROR	Varies	Light		
	_ BLACK TONER SENSOR ERROR	Varies	Light		
	_ NON PAPER SENSE ERROR	Varies	Light	A Sensor output at Paper Empty is outside the spec. Prints according to the Media Weight MIDIUM when this error occurs	
	_ PAPER SENSE ERROR	Varies	Light	The difference in Sensor outputs is outside the spec. (The weight is beyond the recognizable limits.) At Error, Prints according to the Media Weight MEDIUM	
*	BELT REFLEX ERROR	Varies	Light	Belt Reflex Check Error.Error that does not occur at user level.Displayed only in FactoryMode.	
*	DENSITY SHUTTER ERROR2	Varies	Light	Density Adjustment Shutter Error 2.Error that does not occur at user level.Displayed only in FactoryMode.	
*	DENSITY SHUTTER ERROR1	Varies	Light	Density Adjustment Shutter Error 1.Error that does not occur at user level.Displayed only in FactoryMode.	
*	DENSITY COLOR CALIBRATION ERROR	Varies	Light	Density Adjustment Color Calibration Error.Error that does not occur at user level.Displayed only in FactoryMode.	

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
*	DENSITY COLOR SENSOR ERROR	Varies	Light	Density Adjustment Color Sensor Error.Error that does not occur at user level.Displayed only in FactoryMode.	
*	DENSITY BLACK CALIBRATION ERROR	Varies	Light	Density Adjustment Black Calibration Error.Error that does not occur at user level.Displayed only in FactoryMode.	
*	DENSITY BLACK SENSOR ERROR	Varies	Light	Density Adjustment Black Sensor Error.Error that does not occur at user level.Displayed only in FactoryMode.	
*	_ YELLOW IMAGE DRUM SMEAR ERROR	Varies	Light	Density Adjustment C/M/Y/K ID ERROR 2. Smear due to the ID failure.	
*	_ MAGENTA IMAGE DRUM SMEAR ERROR	Varies	Light		
*	_ CYAN IMAGE DRUM SMEAR ERROR	Varies	Light		
*	_ BLACK IMAGE DRUM SMEAR ERROR	Varies	Light		
*	_ YELLOW LOW DENSITY ERROR	Varies	Light	Density Adjustment C/M/Y/K ID ERROR. LED out of focus is assumed.	
*	_ MAGENTA LOW DENSITY ERROR	Varies	Light		
*	_ CYAN LOW DENSITY ERROR	Varies	Light		
*	_ BLACK LOW DENSITY ERROR	Varies	Light		
*	REGISTRATION ERROR1	Varies	Light	Registration Error.This is not user-level error.	
*	SENSOR CALIBRATION ERROR	Varies	Light	Sensor Calibration Error.This is not user-level error.	
*	REGISTRATION ERROR2	Varies	Light	Gamma error(Yellow) This is not user-level error.	
*	REGISTRATION ERROR3	Varies	Light	Gamma error(Magenta) This is not user-level error.	
*	REGISTRATION ERROR4	Varies	Light	Gamma error(Cyan) This is not user-level error.	
*	REGISTRATION ERROR5	Varies	Light	Gamma error(Black) This is not user-level error.	
*	REGISTRATION SENSOR ERROR2	Varies	Light	Registration Sensor Error(Yellow) This is not user-level error.	

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
*	REGISTRATION SENSOR ERROR3	Varies	Light	Registration Sensor Error(Magenta) This is not user-level error.	
*	REGISTRATION SENSOR ERROR4	Varies	Light	Registration Sensor Error(Cyan) This is not user-level error.	
*	REGISTRATION SENSOR ERROR5	Varies	Light	Registration Sensor Error(Black) This is not user-level error.	
	PRESS ONLINE SW COULD NOT STAPLE/PUNCH.TOO THICK PAPER	Varies	Varies	Staple/Punch could not be executed because the media was too thick. This appears when the media too thick to be stapled/punched has been detected. Detection of Transparency falls under this category. Pressing the ONLINE key will clear the message. (R	
	PRESS ONLINE SWCOULD NOT DUPLEX. TOO THICK PAPER	Varies	Varies	Could not perform Duplex printing because the paper is too thick. Displays when paper is detected to be too thick for Duplex printing. The message will disappear when the ONLINE key is pressed.	

3.ES2024/2024E/ES3037/3037e Series (Warning messages : Related to usage, media)

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
	_ ttttt NEAR END	Varies	Varies	The paper in the selected tray is near end.	
	_ YELLOW TONER LOW	Varies	Light	Toner amount is low. Displayed in a combination of other message in the first line. In case of MENU hLOW TONER=STOP, h ATTENTION LED blinks and the printer shifts to OFF Line.When ON-LINE switch is pressed, printing can continue until TONER EMPTY.	
	_ MAGENTA TONER LOW	Varies	Light		
	_ CYAN TONER LOW	Varies	Light		
	_ BLACK TONER LOW	Varies	Light		
	_ YELLOW DRUM NEAR LIFE	Varies	Light	The life of the drum (warning). Displayed in a combination of other message in the first line. The printer stops at the point when it reaches the drum life (Shifts to error, OFF-LINE.)	
	_ MAGENTA DRUM NEAR LIFE	Varies	Light		
	_ CYAN DRUM NEAR LIFE	Varies	Light		
	_ BLACK DRUM NEAR LIFE	Varies	Light		
	_ FUSER UNIT NEAR LIFE	Varies	Light	Notifies the fuser unit is near its life.	
	_ BELT UNIT NEAR LIFE	Varies	Light	Notifies the belt unit is near its life. This is a warning; thus, printing will not stop.	
	_ CHANGE FUSER UNIT	Varies	Light	Notifies the life of the fuser unit (warning). Displayed in a combination of other message in the first line. Warning only (No Life error)	
	_ ttttt EMPTY	Varies	Varies	ttttt: The tray is empty. Treated as Warning until printing to the empty tray is designated.	ttttt:TRAY1~5,MPTRAY
	_ ttttt LIFT UP ERROR	Varies	Varies	Lift Up Error has occurred to tttttt Tray. That tray is treated "Paper Empty" as a result, and printing from that tray becomes disabled. (This sometimes occurs only to PX713.)	ttttt:TRAY1~5
	_ ttttt OVERFILLED	Varies	Varies	Displays that there is too much paper in Tray tttttt. This is a warning; thus, printing will not stop.(This sometimes occurs only to PX713.)	ttttt:TRAY1~5

4.ES2024/2024E/ES3037/3037e Series (Warning messages : Job Account)

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
	FILE ACCESSING	Varies	Varies	Accessing the File System (HDD/FLASH) on the CU board.	
	CANCELLING(USER DENIED)	Blink	Varies	Job cancellation due to no print permit. (Related to JobAccount)1. A job received from a user who is denied printing.2. A color job received from a user who is denied color printing.	
	CANCELLING(BUFFER FULL)	Blink	Light	Indiates that a job has been cancelled because the printer area where the logs are stored has been used up and also "Cancel job" is specified as an operation at the time of Log Full. (Related to JobAccount)	
	_ INVALD ID.JOB REJECTED	Varies	Light	Notifies users that jobs have been cancelled because they are not permitted for printing. (Related to JobAccount). Stays displayed until the ON LINE key is pressed.	
	_ LOG BUFFER FULL.JOB REJECTED	Varies	Light	Notifies users that jobs have been cancelled because the buffer is full. (Related to JobAccount.)Stays displayed until the ON LINE key is pressed.	

5.ES2024/2024E/ES3037/3037e Series (Other Warning)

(Caution)   * : Raise in the factory mode only.

Err Code	LCD Messages	LED Ready	LED Atten	Description	Comments
	DISK FILE SYSTEM IS FULL	Varies	Light	Disk-full is occurring. Because this is a temporary warning, it remains until the end of the job and disappears	
	DISK IS WRITE PROTECTED	Varies	Light	An attempt to write in a read-only file was done. Because this is a temporary warning, it remains until the end of the job and disappears.	
	DISK FILE OPERATION FAILED nnn	Varies	Light	Operation that does not involve a disk is available. nnn: An identifier to Error type (For details, see the Error table provided in the subsequent chapter.)	See right table
	_ JOB OFFSET HOME ERROR	Varies	Light	Job Offset Home Position Sensor ErrorThe Job Offset function becomes disabled, however, printing can continue.	
*	PU FLASH ERROR	Varies	Light	Error occurred while writing over the PU firmware(This does not occur at user level.)	
	COLLATE FAIL:TOO MANY PAGES	Varies	OFF	The data of MOPY is memory-full.	

In case of occourrence of Disk Operation Error, error numbers will be displayed according to individual errors as follows:

Errors	LCD Display	PJL Status Code
GENERAL ERROR	DISK FILE OPERATION FAILED 0	32000
VOLUME NOT AVAILABLE	DISK FILE OPERATION FAILED 1	32001
DISK FULL	DISK FILESYSTEM IS FULL	32002
FILE NOT FOUND	DISK FILE OPERATION FAILED 3	32003
NO FREE FILE DESCRIPTORS	DISK FILE OPERATION FAILED 4	32004
INVALID NUMBER OF BYTES	DISK FILE OPERATION FAILED 5	32005
FILE ALREADY EXISTS	DISK FILE OPERATION FAILED 6	32006
ILLEGAL NAME	DISK FILE OPERATION FAILED 7	32007
CANT DEL ROOT	DISK FILE OPERATION FAILED 8	32008
NOT FILE	DISK FILE OPERATION FAILED 9	32009
NOT DIRECTORY	DISK FILE OPERATION FAILED 10	32010
NOT SAME VOLUME	DISK FILE OPERATION FAILED 11	32011
READ ONLY	DISK FILE OPERATION FAILED 12	32012
ROOT DIR FULL	DISK FILE OPERATION FAILED 13	32013
DIR NOT EMPTY	DISK FILE OPERATION FAILED 14	32014
BAD DISK	DISK FILE OPERATION FAILED 15	32015
NO LABEL	DISK FILE OPERATION FAILED 16	32016
INVALID PARAMETER	DISK FILE OPERATION FAILED 17	32017
NO CONTIG SPACE	DISK FILE OPERATION FAILED 18	32018
CANT CHANGE ROOT	DISK FILE OPERATION FAILED 19	32019
FD OBSOLETE	DISK FILE OPERATION FAILED 20	32020
DELETED	DISK FILE OPERATION FAILED 21	32021
NO BLOCK DEVICE	DISK FILE OPERATION FAILED 22	32022
BAD SEEK	DISK FILE OPERATION FAILED 23	32023
INTERNAL ERROR	DISK FILE OPERATION FAILED 24	32024
WRITE ONLY	DISK FILE OPERATION FAILED 25	32025
WRITE PROTECTED	DISK IS WRITE PROTECTED	32026